



Commodities International  
Shipping and Survey



CISS GROUP UKRAINE LLC  
member of CISS GROUP Pte.Ltd. (Singapore)  
5, Odessa Blv., Ovidiopol district,  
Lymanka village, Odessa region, 65037  
inspection@ciiss-group.com

Page 1/1

CERTIFICATE No.: SGD00957

ORIGINAL

## **HOLDS CLEANLINESS INSPECTION CERTIFICATE**

In pursuance of an order received from our principal, requesting us to carry out inspection we hereby confirm as follows:

Description of goods:	CRUDE SUNFLOWERSEED OIL
Vessel:	MT HIRA V
Quantity:	3100,440 MT
B/L No. & Date:	NO. 1 DD 31.03.2023
Shipper:	SUNOLTA OU KESKLINNA LINNAOSA, JOE TN 4C, 10151, HARJU MAAKOND, TALLINN, ESTONIA
Consignee:	TO THE ORDER
Notify address:	MIGASA ACEITES S.L.U. CARRETERA MADRID – CADIZ KM 556 41703 DOS HERMANAS. SEVILLA. SPAIN.
Port of loading:	IZMAIL, UKRAINE
Port of discharge:	SEVILLE, SPAIN
Vessel Tanks Nos.:	SLOP C-2P-2S-4P-4S-6P-6S

### **RESULTS OF INSPECTION**

We hereby certify that prior to loading the ship's tanks, pumps and pipelines were visually inspected for cleanliness as far as possible and accessible: and were found empty, clean, free from harmful material and in this respect the ships tanks, pumps and pipes are suitable to receive and carry the oil. The last three cargoes as declared by the vessel are as follows:

Ships Tanks N°	Last cargo	Second Last Cargo	Third Last Cargo
1P	CSFO	CSBO	CSFO
1S	CSFO	CSBO	CSFO
2P	HOSO	CSBO	CSFO
2S	HOSO	CSBO	CSFO
3P	CSFO	CSBO	CSFO
3S	CSFO	CSBO	CSFO
4P	HOSO	CSBO	CSFO
4S	HOSO	CSBO	CSFO
5P	CSFO	CSBO	CSFO
5S	CSFO	CSBO	CSFO
6P	HOSO	CSBO	CSFO
6S	HOSO	CSBO	CSFO
SLOP C	HOSO	CSBO	CSFO

These findings are valid for the time and place of inspection only.  
The certificate does not relieve the Vessel, Carrier and any other party from their contractual obligations and duties.

This certificate is electronically signed and stamped.

DATED: 31st of MARCH, 2023

For and on behalf of CISS GROUP Ukraine LLC  
Registered Superintendent and Surveyor Member of FOSFA

