



Commodities International
Shipping and Survey



FOSFA
INTERNATIONAL

Page

1/1

CISS GROUP UKRAINE LLC
member of CISS GROUP Pte.Ltd. (Singapore)
5, Odessa Blv., Ovidiopol district,
Lymanka village, Odessa region, 65037
inspection@ciiss-group.com

CERTIFICATE No.: SGD00957

ORIGINAL

HOLDS CLEANLINESS INSPECTION CERTIFICATE

In pursuance of an order received from our principal, requesting us to carry out inspection we hereby confirm as follows:

Description of goods:	STANDARD CRUDE SUNFLOWER SEED OIL, IN BULK
Vessel:	MT HIRA V
Quantity:	3100,380 MT
B/L No. & Date:	NO. 1 DD 31.03.2023
Shipper:	SUNOLTA OU KESKLINNA LINNAOSA, JOE TN 4C, 10151, HARJU MAAKOND, TALLINN, ESTONIA
Consignee:	TO ORDER
Notify address:	URZANTE SL CIUDAD AGROALIMENTARIA CALLE A AUTOVIA A 68 LOGOÑO-ZARAGOZA, SALIDA 91 31500 TUDELA/SPAIN
Port of loading:	IZMAIL, UKRAINE
Port of discharge:	BILBAO, SPAIN
Vessel Tanks Nos.:	1P-1S-3P-3S-5P-5S

RESULTS OF INSPECTION

We hereby certify that prior to loading the ship's tanks, pumps and pipelines were visually inspected for cleanliness as far as possible and accessible: and were found empty, clean, free from harmful material and in this respect the ships tanks, pumps and pipes are suitable to receive and carry the oil. The last three cargoes as declared by the vessel are as follows:

Ships Tanks N°	Last cargo	Second Last Cargo	Third Last Cargo
1P	CSFO	CSBO	CSFO
1S	CSFO	CSBO	CSFO
2P	HOSO	CSBO	CSFO
2S	HOSO	CSBO	CSFO
3P	CSFO	CSBO	CSFO
3S	CSFO	CSBO	CSFO
4P	HOSO	CSBO	CSFO
4S	HOSO	CSBO	CSFO
5P	CSFO	CSBO	CSFO
5S	CSFO	CSBO	CSFO
6P	HOSO	CSBO	CSFO
6S	HOSO	CSBO	CSFO
SLOP C	HOSO	CSBO	CSFO

These findings are valid for the time and place of inspection only.

The certificate does not relieve the Vessel, Carrier and any other party from their contractual obligations and duties.

This certificate is electronically signed and stamped.

DATED: 31st of MARCH, 2023

For and on behalf of CISS GROUP Ukraine LLC

Registered Superintendent and Surveyor Member of FOSFA

