



Commodities International
Shipping and Survey



Page 1/1

CISS GROUP UKRAINE LLC
member of CISS GROUP Pte.Ltd. (Singapore)
5, Odessa Blv., Ovidiopol district,
Lymanka village, Odessa region, 65037
inspection@ciiss-group.com

CERTIFICATE No.: SGD00960

ORIGINAL

LAST THREE CARGOES CERTIFICATE

In pursuance of an order received from our principal, requesting us to carry out inspection we hereby confirm as follows:

Description of goods:	UKRAINIAN ORIGIN CRUDE SUNFLOWERSEED OIL IN BULK
Vessel:	MT METIN HUSEYNOV
Quantity:	6028,130 MT
B/L No. & Date:	NO. A1-IZMAIL DD 28.03.2023
Shipper:	AVANTAGRO LTD SUITE 1, SECOND FLOOR, SOUND & VISION HOUSE, FRANCIS RACHEL STR., VICTORIA, MAHE, SEYCHELLES ON BEHALF OF VIVACITY MK LLC
Consignee:	TO ORDER
Notify address:	TEAM AGRO GIDA SAN.VE TIC.A.S , BUYUKSEHIR MAH. BEYLIKDUZU CAD. BRAND ISTANBUL PARK B BLOK NO:5/1 DAIRE :2 BEYLIKDUZU/ISTANBUL/TURKIYE.
Port of loading:	IZMAIL, UKRAINE
Port of discharge:	MARMARA or IZMIR Or MERSIN, TURKIYE
Vessel Tanks Nos.:	1, 2, 3, 4, 5, 6, 7, 8, 9,10

RESULTS OF INSPECTION

The last three cargoes as declared by the vessel are as follows:

Ships Tanks N°	Last cargo	Second Last Cargo	Third Last Cargo
1S	ULSD 10 PPM	ULSD 10 PPM	ULSD 10 PPM
2P	ULSD 10 PPM	ULSD 10 PPM	ULSD 10 PPM
3S	ULSD 10 PPM	ULSD 10 PPM	ULSD 10 PPM
4P	ULSD 10 PPM	ULSD 10 PPM	ULSD 10 PPM
5S	ULSD 10 PPM	ULSD 10 PPM	ULSD 10 PPM
6P	ULSD 10 PPM	ULSD 10 PPM	ULSD 10 PPM
7S	ULSD 10 PPM	ULSD 10 PPM	ULSD 10 PPM
8P	ULSD 10 PPM	ULSD 10 PPM	ULSD 10 PPM
9S	ULSD 10 PPM	ULSD 10 PPM	ULSD 10 PPM V
10P	ULSD 10 PPM	ULSD 10 PPM	ULSD 10 PPM

These findings are valid for the time and place of inspection only.

The certificate does not relieve the Vessel, Carrier and any other party from their contractual obligations and duties.

This certificate is electronically signed and stamped.

DATED: 28th of MARCH, 2023

**For and on behalf of CISS GROUP Ukraine LLC
Registered Superintendent and Surveyor Member of FOSFA**

