



Commodities International  
Shipping and Survey



CISS GROUP UKRAINE LLC  
member of CISS GROUP Pte.Ltd. (Singapore)  
5, Odessa Blv., Ovidiopol district,  
Lymanka village, Odessa region, 65037  
inspection@ciiss-group.com

Page 1/1

CERTIFICATE No.: SGD00968

ORIGINAL

## CERTIFICATE STATING LAST 3 CARGOES ARE CLEAN AND UNLEADED

In pursuance of an order received from our principal, requesting us to carry out inspection we hereby confirm as follows:

Description of goods:	STANDARD CRUDE SUNFLOWERSEED OIL, IN BULK
Vessel:	MT DERG
Quantity:	2015,250 MT
B/L No. & Date:	NO. 2 DD 20.04.2023
Shipper:	AVANTAGRO LTD SUITE 1, SECOND FLOOR, SOUND & VISION HOUSE, FRANCIS RACHEL STR., VICTORIA, MAHE, SEYCHELLES ON BEHALF OF SUNOLTA (SUISSE) SA
Consignee:	TO ORDER
Notify address:	F.FAIGES S.L. C/COMERCIO 64 43500 TORTOSA - TARRAGONA (SPAIN)
Port of loading:	IZMAIL, UKRAINE
Port of discharge:	SEVILLE, SPAIN
Vessel Tanks Nos.:	2P, 2S, 3S, 7P, 7S

### RESULTS OF INSPECTION

The last three cargoes as declared by the vessel are as follows:

SHIPS TANKS N°	LAST CARGO	SECOND LAST CARGO	THIRD LAST CARGO
1C	CSFSO	CSFSO	ULSD
2P	CSFSO	JET A-1	ULSD
2S	CSFSO	JET A-1	ULSD
3P	CSFSO	JET A-1	CSFSO
3S	CSFSO	JET A-1	CSFSO
4P	CSFSO	JET A-1	CSFSO
4S	CSFSO	JET A-1	CSFSO
5P	CSFSO	JET A-1	CSFSO
5S	CSFSO	JET A-1	CSFSO
6P	CSFSO	JET A-1	CSFSO
6S	CSFSO	JET A-1	CSFSO
7P	CSFSO	CSFSO	ULSD
7S	CSFSO	CSFSO	CSFSO

These findings are valid for the time and place of inspection only.

The certificate does not relieve the Vessel, Carrier and any other party from their contractual obligations and duties.

**This certificate is electronically signed and stamped.**

DATED: 20th of APRIL, 2023

For and on behalf of CISS GROUP Ukraine LLC  
Registered Superintendent and Surveyor Member of FOSFA

