

**FOSFA COMBINED MASTERS CERTIFICATE**

Ship	MT DERG	Voyage No	04/23
Year Built	2008	Official No	9393060
Owners	ARSLAND DERG LTD	Operator	BESIKTAS LIKID TASIMACILIK DENIZCILIK
In respect of carriage of (tonnage)	3042,660 MT	Description	Ukrainian Crude Sunflowerseed oil in Bulk
Loaded/Ex Transhipment at	IZMAIL, UKRAINE (Load Port)	For shipment to	SEVILLE, SPAIN (Discharge Port)

In Ships Tanks No(s) 1C, 3P, 5P, 5S  
 AVANTAGRO LTD  
 SUITE 1, SECOND FLOOR, SOUND & VISION HOUSE,  
 FRANCIS RACHEL STR., VICTORIA, MAHE, SEYCHELLES  
 \*Shippers/Charterers ON BEHALF OF SUNOLTA (SUISSE) SA

I state that -

- The above named vessel is classed with (Society) Bureau Veritas Certificate No. ITB0/SZD/20230405135515  
 issued at Istanbul, Turkey dated 06.04.2023 which currently remains in force.  
 The oil tight integrity of all cargo compartments is a condition of such classification.
- The named ship complies with the FOSFA Qualifications and Operational Procedures for Ships Engaged in the Carriage of Oils and Fats in Bulk for Edible and Oleo-Chemical use.
- Tank heating is by ~~\*immersed coils~~/heat exchangers. Coils, tubes and shell as applicable are of stainless steel construction, and were tested on 12.04.2023 (date) to not less than 7,5 kPa / bars for a period of 10 minutes and found tight.
- Copper and its alloys such as brass, bronze or gun metal are not present in any part of the system installation and means of transport that has contact with the oils or fats.
- Tank access/cleaning hatches are staunch and tight with suitable packing and gaskets compatible with the cargo.
- All internal structural members are self-draining.
- Tank(s) is (are) ~~\*mild steel~~/mild steel coated/~~stainless steel construction~~.
- Where applicable tank coating(s) is (are) Marine Line which is (are) fit for food grade products/carriage of oils and fats.
- In the tank heating system, heating medium is ~~\*hot water, live steam~~.
- ~~For contamination control purposes, if the vessel also has a thermal heating fluid system, the thermal heating fluid is~~
- Cargo lines are ~~\*stainless steel~~/mild steel with sufficient drain valves to ensure complete clearing and draining of the system.
- The tank(s) has (have) not contained, as the last three cargoes, any leaded products.
- Cargo History - the previous cargoes were as follows:

Ships Tanks No	Last Cargo	Second Last Cargo	Third Last Cargo	Etc
1C	CSFSO	CSFSO	ULSD	
3P	CSFSO	JET A-1	CSFSO	
5P	CSFSO	JET A-1	CSFSO	
5S	CSFSO	JET A-1	CSFSO	

In the event that a cargo was less than 60% of volume of the tank, such cargo to be recorded but is not to be considered a qualifying previous cargo. Such cargo not to be a product on the FOSFA List of Banned Immediate Previous Cargoes or to be a product on the FOSFA List of Acceptable Previous Cargoes; whichever list to apply, dictated by the sales contract.

14. Subject tanks have been cleaned after immediate previous cargoes using cleaning methods as noted below:

1-BW with ambient sea water for 30 min;  
 2-BW with hot FW for 2 hrs;  
 3-Rinsing with ambient FW for 30 min;  
 4-Well draining (pumps, lines, manifold), vent, mop, dry

15. Subject tank ~~were~~/ were not \*re-coated prior to loading.

All information in the Combined Masters Certificate obtained from the vessel representative is the sole responsibility of the vessel.

Signed  
 Ship MT DERG  
 Date 16.04.2023  
 \*Delete which is inapplicable.

\*Captain/Chief Officer

YILMAZ SABIT

