





Page

CISS GROUP UKRAINE LLC member of CISS GROUP Pte.Ltd. (Singapore) 5, Odessa Blv., Ovidiopol district, Lymanka village, Odessa region, 65037 inspection@ciss-group.com

Port of loading:

CERTIFICATE No.: SGD00968

ORIGINAL

CERTIFICATE STATING LAST 3 CARGOES ARE CLEAN AND UNLEADED AND NOT IN BANNED LIST

In pursuance of an order received from our principal, requesting us to carry out inspection we hereby confirm as follows:

Description of goods: STANDARD CRUDE SUNFLOWER SEED OIL, IN BULK

Vessel: MT DERG Quantity: 3150,000 MT

B/L No. & Date: NO. 1 DD 20.04.2023 Shipper: AVANTAGRO LTD

> SUITE 1, SECOND FLOOR, SOUND & VISION HOUSE, FRANCIS RACHEL STR., VICTORIA, MAHE, SEYCHELLES

ON BEHALF OF SUNOLTA (SUISSE) SA

Consignee: TO ORDER **URZANTE SL** Notify address:

CIUDAD AGROALIMENTARIA CALLE A

AUTOVIA A 68 LOGOÑO-ZARAGOZA, SALIDA 91 31500

TUDELA/SPAIN IZMAIL, UKRAINE

Port of discharge: BILBAO, SPAIN Vessel Tanks Nos.: 4P, 4S, 6P, 6S

RESULTS OF INSPECTION

The last three cargoes as declared by the vessel are as follows:

SHIPS TANKS N°	LAST CARGO	SECOND LAST CARGO	THIRD LAST CARGO
1C	CSFSO	CSFSO	ULSD
2P	CSFSO	JET A-1	ULSD
2S	CSFSO	JET A-1	ULSD
3P	CSFSO	JET A-1	CSFSO
3S	CSFSO	JET A-1	CSFSO
4P	CSFSO	JET A-1	CSFSO
4S	CSFSO	JET A-1	CSFSO
5P	CSFSO	JET A-1	CSFSO
5S	CSFSO	JET A-1	CSFSO
6P	CSFSO	JET A-1	CSFSO
6S	CSFSO	JET A-1	CSFSO
7P	CSFSO	CSFSO	ULSD
78	CSFSO	CSFSO	CSFSO

These findings are valid for the time and place of inspection only.

The certificate does not relieve the Vessel, Carrier and any other party from their contractual obligations and duties.

This certificate is electronically signed and stamped.

DATED: 20th of APRIL, 2023 For and on behalf of CISS GROUP Ukraine LLC Registered Superintendent and Surveyor Member of FOSFA



