





Page

1/1

CISS GROUP UKRAINE LLC member of CISS GROUP Pte.Ltd. (Singapore) 5, Odessa Blv., Ovidiopol district, Lymanka village, Odessa region, 65037 inspection@ciss-group.com

CERTIFICATE No.: SGD00968

ORIGINAL

TANKS CLEANLINESS INSPECTION CERTIFICATE

In pursuance of an order received from our principal, requesting us to carry out inspection we

hereby confirm as follows:

Description of goods: STANDARD CRUDE SUNFLOWERSEED OIL, IN BULK

Vessel: MT DERG Quantity: 2015.250 MT

B/L No. & Date: NO. 2 DD 20.04.2023 **AVANTAGRO LTD** Shipper:

SUITE 1, SECOND FLOOR, SOUND & VISION HOUSE FRANCIS RACHEL STR., VICTORIA, MAHE, SEYCHELLES

ON BEHALF OF SUNOLTA (SUISSE) SA

Consignee: TO ORDER Notify address: F.FAIGES S.L. C/COMERCIO 64

43500 TORTOSA - TARRAGONA (SPAIN)

Port of loading: IZMAIL, UKRAINE Port of discharge: SEVILLE, SPAIN Vessel Tanks Nos.: 2P, 2S, 3S, 7P, 7S

RESULTS OF INSPECTION

We hereby certify that prior to loading the ship's tanks, pumps and pipelines were visually inspected for cleanliness as far as possible and accessible: and were found empty, clean, free from harmful material and in this respect the ships tanks, pumps and pipes are suitable to receive and carry the oil. The last three cargoes as declared by the vessel are as follows:

SHIPS TANKS N°	LAST CARGO	SECOND LAST CARGO	THIRD LAST CARGO
1C	CSFSO	CSFSO	ULSD
2P	CSFSO	JET A-1	ULSD
2S	CSFSO	JET A-1	ULSD
3P	CSFSO	JET A-1	CSFSO
3S	CSFSO	JET A-1	CSFSO
4P	CSFSO	JET A-1	CSFSO
4S	CSFSO	JET A-1	CSFSO
5P	CSFSO	JET A-1	CSFSO
5S	CSFSO	JET A-1	CSFSO
6P	CSFSO	JET A-1	CSFSO
6S	CSFSO	JET A-1	CSFSO
7P	CSFSO	CSFSO	ULSD
7S	CSFSO	CSFSO	CSFSO

These findings are valid for the time and place of inspection only.

The certificate does not relieve the Vessel, Carrier and any other party from their contractual obligations and duties.

This certificate is electronically signed and stamped.

DATED: 20th of APRIL, 2023 For and on behalf of CISS GROUP Ukraine LLC Registered Superintendent and Surveyor Member of FOSFA



