





CISS GROUP UKRAINE LLC
member of CISS GROUP Pte.Ltd. (Singapore)
5, Odessa Blv., Ovidiopol district,
Lymanka village, Odessa region, 65037
inspection@ciss-group.com

**CERTIFICATE No.: SGD01020** 

**ORIGINAL** 

## TANK INSPECTION CERTIFICATE

In pursuance of an order received from our principal, requesting us to carry out inspection we hereby confirm as follows:

Description of goods: CRUDE SUNFLOWER SEED OIL UKRAINE ORIGIN, IN BULK

FOR FOOD USE AFTER APPROPRIATE REFINING

Vessel: MT DENSA DEFNE

Quantity: 6600,000 MT

B/L No. & Date: NO. 1 AND 2 DD 06.06.2023 Shipper: SUNOLTA (SUISSE) SA

RUE DU 23-JUIN 26, 2800 DELEMONT, SWITZERLAND

REG.NO. CHE-345.676.000 VAT. No. CHE-345.676.000 TVA

Consignee: TO THE ORDER

Notify address: CASA OLEARIA ITALIANA S.P.A

**VIA BAIONE 200** 

70043 MONOPOLI (BARI)

Port of loading: IZMAIL, UKRAINE
Port of discharge: MONOPOLI, ITALY

Vessel Tanks Nos.: 1P, 2P, 3P, 4P, 5P, 6P, 1S, 2S, 3S, 4S, 5S, 6S

## RESULTS OF INSPECTION

We hereby certify that prior to loading the ship's tanks, pumps and pipelines were visually inspected for cleanliness as far as possible and accessible: and were found empty, clean, free from harmful material and in this respect the ships tanks, pumps and pipes are suitable to receive and carry the oil. The last three cargoes as declared by the vessel are as follows:

SHIPS TANKS N°	LAST CARGO	SECOND LAST CARGO	THIRD LAST CARGO
1P	CSFSO 96%	ULSD 10 PPM 98%	STANDART CSFSO 97%
1S	CSFSO 96%	ULSD 10 PPM 98%	STANDART CSFSO 97%
2P	CSFSO 97%	ULSD 10 PPM 98%	UKRAINIAN CSFSO 95%
2S	CSFSO 97%	ULSD 10 PPM 98%	UKRAINIAN CSFSO 95%
3P	CSFSO 97%	ULSD 10 PPM 98%	UKRAINIAN CSFSO 88%
3S	CSFSO 97%	ULSD 10 PPM 98%	UKRAINIAN CSFSO 88%
4P	CSFSO 95%	ULSD 10 PPM 98%	STANDART CSFSO 97%
4S	CSFSO 95%	ULSD 10 PPM 98%	STANDART CSFSO 96%
5P	CSFSO 87%	ULSD 10 PPM 98%	UKRAINIAN CSFSO 64%
5S	CSFSO 87%	ULSD 10 PPM 98%	UKRAINIAN CSFSO 64%
6P	CSFSO 68%	ULSD 10 PPM 98%	STANDART CSFSO 92%
6S	CSFSO 77%	ULSD 10 PPM 98%	STANDART CSFSO 82%

These findings are valid for the time and place of inspection only.

The certificate does not relieve the Vessel, Carrier and any other party from their contractual obligations and duties.

This certificate is electronically signed and stamped.

Re

DATED: 6th of JUNE, 2023
For and on behalf of CISS GROUP Ukraine LLC
Registered Superintendent and Surveyor Member of FOSFA





This certificate is issued to any job or services carried out within the GENERAL TERMS AND CONDITION OF BUSINESS printed overleaf. This certificate is not intended to relieve the parties of any relevant sales contract from their contractual obligations. The Company's responsibility under this Certificate is limited to proven negligence and will in no case be more then ten times the amount of the fees