







CISS GROUP UKRAINE LLC member of CISS GROUP Pte.Ltd. (Singapore) 5, Odessa Blv., Ovidiopol district, Lymanka village, Odessa region, 65037 Inspection@ciss-group.com

CERTIFICATE No.: SGD01037

ORIGINAL

CERTIFICATE STATING LAST 3 CARGOES ARE CLEAN AND UNLEADED

In pursuance of an order received from our principal, requesting us to carry out inspection we

hereby confirm as follows:

Description of goods: UKRAINIAN CRUDE SUNFLOWERSEEDOIL IN BULK

Vessel: MT MRC LINA Quantity: 2732,530 MT

B/L No. & Date: NO. A1-IZMAIL DD 21.06.2023 Shipper: SUNOLTA (SUISSE) SA

RUE DU 23-JUIN 26, 2800 DELEMONT, SWITZERLAND

REG.NO. CHE-345.676.000

Consignee: TO ORDER

Notify address: SOVENA OILSEEDS PORTUGAL SA

RUA DR. ANTÓNIO LOUREIRO BORGES, Nº2

EDIFICIO ARQUIPARQUE, Nº2-3º

MIRAFLORES 1495-131 ALGÉS - PORTUGAL

Port of loading: IZMAIL, UKRAINE Port of discharge: SEVILLE, SPAIN

Vessel Tanks Nos.: 1P/S, 4P/S

RESULTS OF INSPECTION

The last three cargoes as declared by the vessel are as follows:

	SHIPS TANKS N°	LAST CARGO	SECOND LAST CARGO	THIRD LAST CARGO
	1P	METHANOL 89%	METHANOL 90%	METHANOL 88%
1	18	METHANOL 88%	METHANOL 91%	METHANOL 87%
	4P	METHANOL 90%	METHANOL 94%	METHANOL 90%
	4S	METHANOL 89%	METHANOL 95%	METHANOL 89%

These findings are valid for the time and place of inspection only.

The certificate does not relieve the Vessel, Carrier and any other party from their contractual obligations and duties.

This certificate is electronically signed and stamped.

DATED: 21st of JUNE, 2023 For and on behalf of CISS GROUP Ukraine LLC Registered Superintendent and Surveyor Member of FOSFA





