

**CERTIFICATE No.: SGD01037** 





Page

1/1

CISS GROUP UKRAINE LLC member of CISS GROUP Pte.Ltd. (Singapore) 5, Odessa Blv., Ovidiopol district, Lymanka village, Odessa region, 65037 inspection@ciss-group.com

ORIGINAL

## HOLDS CLEANLINESS INSPECTION CERTIFICATE

In pursuance of an order received from our principal, requesting us to carry out inspection we

hereby confirm as follows:

Description of goods: STANDARD CRUDE SUNFLOWER SEED OIL, IN BULK

Vessel: MT MRC LINA Quantity: 3850,000 MT

B/L No. & Date: NO. A2-IZMAIL AND A3-IZMAIL DD 21.06.2023

Shipper: SUNOLTA (SUISSE) SA

RUE DU 23-JUIN 26, 2800 DELEMONT, SWITZERLAND

REG.NO. CHE-345.676.000

Consignee: TO ORDER
Notify address: URZANTE SL

CIUDAD AGROALIMENTARIA CALLE A

AUTOVIA A 68 LOGOÑO-ZARAGOZA, SALIDA 91 31500

TUDELA/SPAIN

Port of loading: IZMAIL, UKRAINE
Port of discharge: BILBAO, SPAIN
Vessel Tanks Nos.: 2 P/S, 3 P/S, 6 P/S

## **RESULTS OF INSPECTION**

We hereby certify that prior to loading the ship's tanks, pumps and pipelines were visually inspected for cleanliness as far as possible and accessible: and were found empty, clean, free from harmful material and in this respect the ships tanks, pumps and pipes are suitable to receive and carry the oil. The last three cargoes as declared by the vessel are as follows:

SHIPS TANKS N°	LAST CARGO	SECOND LAST CARGO	THIRD LAST CARGO
2P	METHANOL 90%	GASOLINE 96%	GASOLINE 96%
2S	METHANOL 91%	GASOLINE 96%	GASOLINE 95%
3P	METHANOL 91%	METHANOL 90%	METHANOL 92%
3S	METHANOL 92%	METHANOL 89%	METHANOL 92%
6P	METHANOL 94%	GASOLINE 93%	VEGOIL 92%
6S	METHANOL 95%	GASOLINE 92%	VEGOIL 89%

These findings are valid for the time and place of inspection only.

The certificate does not relieve the Vessel, Carrier and any other party from their contractual obligations and duties.

This certificate is electronically signed and stamped.

DATED: 21st of JUNE, 2023
For and on behalf of CISS GROUP Ukraine LLC
Registered Superintendent and Surveyor Member of FOSFA





