







raye

CERTIFICATE No.: SGD01042

ORIGINAL

CISS GROUP UKRAINE LLC member of CISS GROUP Pte.Ltd. (Singapore) 5, Odessa Blv., Ovidiopol district, Lymanka village, Odessa region, 65037 inspection@ciss-group.com

TANK CLEANLINESS CERTIFICATE

In pursuance of an order received from our principal, requesting us to carry out inspection we hereby confirm as follows:

Description of goods: UKRAINIAN CRUDE SUNFLOWER OIL IN BULK

Vessel: MT SCOT STUTTGART

Quantity: 6570,510 MT

B/L No. & Date: NO. A1-IZMAIL DD 29.06.2023

Shipper: SUNOLTA OU

HARJU MAAKOND, TALLINN, KESKLINNA LINNAOSA, JÖE TN

4C 10151 ESTONIA

Consignee: "TAMPIERI SPA – VIA GRANAROLO N. 177/3 – 48018 FAENZA

RAVENNA - ITALY"

Notify address: "TAMPIERI SPA – VIA GRANAROLO N. 177/3 – 48018 FAENZA

RAVENNA - ITALY"

Port of loading: IZMAIL, UKRAINE
Port of discharge: RAVENNA, ITALY

Vessel Tanks Nos.: 1 P/S, 2 P/S, 3 P/S, 4 P/S, 5 P/S, 6 P/S

RESULTS OF INSPECTION

We hereby certify that prior to loading the ship's tanks, pumps and pipelines were visually inspected for cleanliness as far as possible and accessible: and were found empty, clean, free from harmful material and in this respect the ships tanks, pumps and pipes are suitable to receive and carry the oil. The last three cargoes as declared by the vessel are as follows:

Ships Tanks N°	Last cargo	Second Last Cargo	Third Last Cargo
1P	SUNFLOWER SEED OIL 70,0%	GASOLINE 96,7%	SUNFLOWER SEED OIL 76,2%
18	SUNFLOWER SEED OIL 71,0%	GASOLINE 95,3%	SUNFLOWER SEED OIL 72,5%
2P	SUNFLOWER SEED OIL 82,4%	GASOLINE 96,9%	SUNFLOWER SEED OIL 83,8%
2S	SUNFLOWER SEED OIL 83,3%	GASOLINE 97,3%	SUNFLOWER SEED OIL 85,4%
3P	SUNFLOWER SEED OIL 81,6%	GASOLINE 97,7%	SUNFLOWER SEED OIL 84,6%
3S	SUNFLOWER SEED OIL 81,6%	GASOLINE 97,7%	SUNFLOWER SEED OIL 79,8%
4P	SUNFLOWER SEED OIL 83,0%	GASOLINE 97,7%	SUNFLOWER SEED OIL 81,3%
4S	SUNFLOWER SEED OIL 78,1%	GASOLINE 97,7%	SUNFLOWER SEED OIL 80,6%
5P	SUNFLOWER SEED OIL 87,0%	GASOLINE 96,7%	SUNFLOWER SEED OIL 84,6%
5S	SUNFLOWER SEED OIL 86,9%	GASOLINE 95,8%	SUNFLOWER SEED OIL 86,6%
6P	SUNFLOWER SEED OIL 94,4%	GASOLINE 95,8%	SUNFLOWER SEED OIL 94,5%
6S	SUNFLOWER SEED OIL 93,8%	GASOLINE 95,8%	SUNFLOWER SEED OIL 94,9%

These findings are valid for the time and place of inspection only.

The certificate does not relieve the Vessel, Carrier and any other party from their contractual obligations and duties.

This certificate is electronically signed and stamped.

Continue of the state of the st

DATED: 29th of JUNE, 2023
For and on behalf of CISS GROUP Ukraine LLC
Registered Superintendent and Surveyor Member of FOSFA



