Commodities International Shipping and Survey







CISS GROUP UKRAINE LLC member of CISS GROUP Pte.Ltd. (Singapore)

5, Odessa Blv., Ovidiopol district, Lymanka village, Odessa region, 65037 inspection@ciss-group.com

CERTIFICATE No.: SGD01045

ORIGINAL

CERTIFICATE STATING LAST 3 CARGOES

In pursuance of an order received from our principal, requesting us to carry out inspection we hereby confirm as follows:

Description of goods: Ukrainian Crude Sunflowerseedoil in Bulk

Vessel: MT DENSA DEFNE Quantity: 6598,280 MT

B/L No. & Date: NO. 1, 2 DD 30.06.2023 Shipper: SUNOLTA (SUISSE) SA

SUNOLTA (SUISSE) SA RUE DU 23-JUIN 26, 2800 DELEMONT, SWITZERLAND

REG.NO. CHE-345.676.000

Consignee: TO ORDER

Notify address: Sovena Oilseeds Portugal Sa

Rua Dr. António Loureiro Borges, nº2

Edificio Arquiparque, nº2-3º

Miraflores 1495-131 Algés - Portugal

Port of loading: IZMAIL, UKRAINE
Port of discharge: SEVILLE, SPAIN

Vessel Tanks Nos.: 1P, 1S, 2P, 2S, 3P, 3S, 4P, 4S, 5P, 5S, 6P, 6S.

RESULTS OF INSPECTION

The last three cargoes as declared by the vessel are as follows:

Ships Tanks N°	Last cargo	Second Last Cargo	Third Last Cargo
1P	CSFSO 96%	CSFSO 96%	ULSD10 PPM 98%
1S	CSFSO 96%	CSFSO 96%	ULSD10 PPM 98%
2P	CSFSO 96%	CSFSO 97%	ULSD10 PPM 98%
2S	CSFSO 96%	CSFSO 97%	ULSD10 PPM 98%
3P	CSFSO 92%	CSFSO 97%	ULSD10 PPM 98%
3S	CSFSO 92%	CSFSO 97%	ULSD10 PPM 98%
4P	CSFSO 95%	CSFSO 95%	ULSD10 PPM 98%
4S	CSFSO 95%	CSFSO 95%	ULSD10 PPM 98%
5P	CSFSO 96%	CSFSO 87%	ULSD10 PPM 98%
5S	CSFSO 96%	CSFSO 87%	ULSD10 PPM 98%
6P	CSFSO 83%	CSFSO 68%	ULSD10 PPM 98%
6S	CSFSO 83%	CSFSO 77%	ULSD10 PPM 98%

These findings are valid for the time and place of inspection only.

The certificate does not relieve the Vessel, Carrier and any other party from their contractual obligations and duties.

This certificate is electronically signed and stamped.

DATED: 30th of JUNE, 2023

For and on behalf of CISS GROUP Ukraine LLC

Registered Superintendent and Surveyor Member of FOSFA





