



Commodities International
Shipping and Survey



Page 1/2

CISS GROUP UKRAINE LLC
member of CISS GROUP Pte.Ltd. (Singapore)
5, Odessa Blv., Ovidiopol district,
Lymanka village, Odessa region, 65037
inspection@ciiss-group.com

CERTIFICATE No.: SGD01061

ORIGINAL

TANK INSPECTION CERTIFICATE

In pursuance of an order received from our principal, requesting us to carry out inspection we hereby confirm as follows:

Description of goods:	CRUDE SUNFLOWER SEED OIL UKRAINE ORIGIN, IN BULK FOR FOOD USE AFTER APPROPRIATE REFINING
Vessel:	MT VITIS
Quantity:	5897,020 MT
B/L No. & Date:	NO. A1-IZMAIL AND A2-IZMAIL DD 25.07.2023
Shipper:	SUNOLTA (SUISSE) SA RUE DU 23-JUIN 26, 2800 DELEMONT, SWITZERLAND REG.NO. CHE-345.676.000
Consignee:	TO THE ORDER
Notify address:	CASA OLEARIA ITALIANA S.P.A VIA BAIONE 200 70043 MONOPOLI (BARI)
Port of loading:	IZMAIL, UKRAINE
Port of discharge:	MONOPOLI, ITALY
Vessel Tanks Nos.:	1W, 2W, 3W, 4W, 5W, 6W, 7W, 8W, 9W, 10W, 11W

RESULTS OF INSPECTION

We hereby certify that prior to loading the ship's tanks, pumps and pipelines were visually inspected for cleanliness as far as possible and accessible: and were found empty, clean, free from harmful material and in this respect the ships tanks, pumps and pipes are suitable to receive and carry the oil. The last three cargoes as declared by the vessel are as follows:

SHIPS TANKS N°	LAST CARGO	SECOND LAST CARGO	THIRD LAST CARGO
1P	CSFO 98%	CSFO 98%	CSFO 98%
1S	CSFO 98%	CSFO 98%	CSFO 98%
2P	CSFO 98%	CSFO 98%	CSFO 98%
2S	CSFO 98%	CSFO 98%	CSFO 98%
3P	CSFO 98%	CSFO 98%	CSFO 98%
3S	CSFO 98%	CSFO 98%	CSFO 98%
4P	CSFO 98%	CSFO 98%	CSFO 98%
4S	CSFO 98%	CSFO 98%	CSFO 98%
5P	SOYA 98%	CSFO 98%	CSFO 98%
5S	SOYA 98%	CSFO 98%	CSFO 98%





**Commodities International
Shipping and Survey**



Page 2/2

CISS GROUP UKRAINE LLC
member of **CISS GROUP Pte.Ltd. (Singapore)**
5, Odessa Blv., Ovidiopol district,
Lymanka village, Odessa region, 65037
inspection@ciiss-group.com

CERTIFICATE No.: SGD01061

ORIGINAL

6P	SOYA 98%	CSFO 98%	CSFO 98%
6S	SOYA 98%	CSFO 98%	CSFO 98%
7P	CSFO 98%	CSFO 98%	CSFO 98%
7S	CSFO 98%	CSFO 98%	CSFO 98%
8P	CSFO 98%	CSFO 98%	CSFO 98%
8S	CSFO 98%	CSFO 98%	CSFO 98%
9P	SOYA 98%	CSFO 98%	CSFO 98%
9S	SOYA 98%	CSFO 98%	CSFO 98%
10P	CSFO 98%	CSFO 98%	CSFO 98%
10S	CSFO 98%	CSFO 98%	CSFO 98%
11P	SOYA 98%	CSFO 98%	CSFO 98%
11S	SOYA 98%	CSFO 98%	CSFO 98%

These findings are valid for the time and place of inspection only.
The certificate does not relieve the Vessel, Carrier and any other party from their contractual obligations and duties.

This certificate is electronically signed and stamped.
DATED: 25th of JULY, 2023
For and on behalf of CISS GROUP Ukraine LLC
Registered Superintendent and Surveyor Member of FOSFA



This certificate is issued to any job or services carried out within the GENERAL TERMS AND CONDITION OF BUSINESS printed overleaf. This certificate is not intended to relieve the parties of any relevant sales contract from their contractual obligations. The Company's responsibility under this Certificate is limited to proven negligence and will in no case be more than ten times the amount of the fees.