



CISS GROUP UKRAINE LLC
member of CISS GROUP Pte.Ltd. (Singapore)
5, Odessa Blv., Ovidiopol district,
Lymanka village, Odessa region, 65037
Inspection@ciss-group.com

CERTIFICATE No.: SGD01067

ORIGINAL

LAST THREE CARGOES CERTIFICATE

In pursuance of an order received from our principal, requesting us to carry out inspection we hereby confirm as follows:

Description of goods:	UKRAINIAN ORIGIN CRUDE SUNFLOWER SEED OIL IN BULK
Vessel:	MT KHUDAYAR YUSIFZADE
Quantity:	6580,022 MT
B/L No. & Date:	NO. A1-IZMAIL AND A2-IZMAIL DD 09.08.2023
Shipper:	SUNOLTA (SUISSE) SA RUE DU 23-JUIN 26, 2800 DELEMONT, SWITZERLAND REG.NO. CHE-345.676.000
Consignee:	TO ORDER
Notify address:	ABALIOGLU YAG SANAYI VE TICARET A.S. 10006/1 SOKAK NO:19 A.O.S.B. CIGLI, IZMIR – TURKEY
Port of loading:	IZMAIL, UKRAINE
Port of discharge:	ALIAGA, TURKEY
Vessel Tanks Nos.:	CT1, CT 2, CT 3, CT 4, CT 5, CT 6

RESULTS OF INSPECTION

The last three cargoes as declared by the vessel are as follows:

SHIPS TANKS N°	LAST CARGO	SECOND LAST CARGO	THIRD LAST CARGO
1C	ULSD 10 PPM	GASOLINE	SUNFLOWER SEED OIL
2C	ULSD 10 PPM	GASOLINE	SUNFLOWER SEED OIL
3C	ULSD 10 PPM	GASOLINE	SUNFLOWER SEED OIL
4C	ULSD 10 PPM	GASOLINE	SUNFLOWER SEED OIL
5C	ULSD 10 PPM	GASOLINE	SUNFLOWER SEED OIL
6C	ULSD 10 PPM	GASOLINE	SUNFLOWER SEED OIL

These findings are valid for the time and place of inspection only.

The certificate does not relieve the Vessel, Carrier and any other party from their contractual obligations and duties.

This certificate is electronically signed and stamped.

DATED: 9th of AUGUST, 2023

For and on behalf of CISS GROUP Ukraine LLC
Registered Superintendent and Surveyor Member of FOSFA

