







Page

1/1

CISS GROUP UKRAINE LLC member of CISS GROUP Pte.Ltd. (Singapore) 5, Odessa Blv., Ovidiopol district, Lymanka village, Odessa region, 65037 inspection@ciss-group.com

CERTIFICATE No.: SGD01142

ORIGINAL

3 LAST CARGO CERTIFICATE

In pursuance of an order received from our principal, requesting us to carry out inspection we hereby confirm as follows:

Description of goods: CRUDE SUNFLOWER SEED OIL OF EDIBLE GRADE, IN BULK

Vessel: MT JABRAYIL DOVLATZADEH

Quantity: 2948,840 MT

B/L No. & Date: NO. A1-IZMAIL DD 29.09.2023 SUNOLTA (SUISSE) SA Shipper:

RUE DU 23-JUIN 26, 2800 DELEMONT, SWITZERLAND

REG.NO. CHE-345.676.000

Consignee: TO ORDER Notify address: OLIVA AD

SOFIA, BULGARIA,

LOZENETS DISTRICT, 1407, **60 ASEN YORDANOV STREET**

VAT: BG106013774

Port of loading: IZMAIL, UKRAINE Port of discharge: VARNA, BULGARIA

Vessel Tanks Nos.: 2 P/S, 3 P/S, 4 P/S, 5 P/S, 6 P/S

RESULTS OF INSPECTION

The last three cargoes as declared by the vessel are as follows:

SHIPS TANKS N°	LAST CARGO	SECOND LAST CARGO	THIRD LAST CARGO
2P	ULSD 10 PPM	ULSD 10 PPM	ULSD 10 PPM
28	ULSD 10 PPM	ULSD 10 PPM	ULSD 10 PPM
3P	ULSD 10 PPM	ULSD 10 PPM	ULSD 10 PPM
3\$	ULSD 10 PPM	ULSD 10 PPM	ULSD 10 PPM
4P	ULSD 10 PPM	ULSD 10 PPM	ULSD 10 PPM
48	ULSD 10 PPM	ULSD 10 PPM	ULSD 10 PPM
5P	ULSD 10 PPM	ULSD 10 PPM	ULSD 10 PPM
5S	ULSD 10 PPM	ULSD 10 PPM	ULSD 10 PPM
6P	ULSD 10 PPM	ULSD 10 PPM	ULSD 10 PPM
6S	ULSD 10 PPM	ULSD 10 PPM	ULSD 10 PPM

These findings are valid for the time and place of inspection only.

The certificate does not relieve the Vessel, Carrier and any other party from their contractual obligations and duties.

This certificate is electronically signed and stamped.

DATED: 29th of SEPTEMBER, 2023 For and on behalf of CISS GROUP Ukraine LLC Registered Superintendent and Surveyor Member of FOSFA





