



Commodities International
Shipping and Survey



FOSFA
INTERNATIONAL

Page 1/1

CISS GROUP UKRAINE LLC
member of CISS GROUP Pte.Ltd. (Singapore)
5, Odessa Blv., Ovidiopol district,
Lymanka village, Odessa region, 65037
inspection@ciiss-group.com

CERTIFICATE No.: SGD01159

ORIGINAL

TANK CLEANLINESS CERTIFICATE

In pursuance of an order received from our principal, requesting us to carry out inspection we hereby confirm as follows:

| | |
|-----------------------|--|
| Description of goods: | UKRAINIAN ORIGIN CRUDE SUNFLOWER SEED OIL - IN BULK |
| Vessel: | MT ELIANA |
| Quantity: | 5098,800 MT |
| B/L No. & Date: | NO. 1 UPSS DD 27.10.2023 SUNOLTA (SUISSE) SA |
| Shipper: | RUE DU 23-JUIN 26, 2800 DELEMONT, SWITZERLAND REG.NO. CHE-345.676.000 |
| Consignee: | TO ORDER |
| Notify address: | VITERRA B.V BLAAK 31, 3011 GA ROTTERDAM/ THE NETHERLANDS |
| Port of loading: | IZMAIL, UKRAINE |
| Port of discharge: | Mersin or Savka or WIMBA Terminal or Iskenderun, Turkey |
| Vessel Tanks Nos.: | 1P/S-2P/S-3P/S-4P/S-5P/S |

RESULTS OF INSPECTION

We hereby certify that prior to loading the ship's tanks, pumps and pipelines were visually inspected for cleanliness as far as possible and accessible: and were found empty, clean, free from harmful material and in this respect the ships tanks, pumps and pipes are suitable to receive and carry the oil. The last three cargoes as declared by the vessel are as follows:

| SHIPS TANKS N° | LAST CARGO | SECOND LAST CARGO | THIRD LAST CARGO |
|----------------|------------|-------------------|------------------|
| 1P | ULSD 97,4% | JET A-1 97,4% | ULSD 95,0% |
| 1S | ULSD 97,4% | JET A-1 97,4% | ULSD 95,0% |
| 2P | ULSD 97,4% | JET A-1 97,4% | ULSD 95,0% |
| 2S | ULSD 97,4% | JET A-1 97,4% | ULSD 95,0% |
| 3P | ULSD 97,4% | JET A-1 97,4% | ULSD 70,5% |
| 3S | ULSD 97,4% | JET A-1 97,4% | ULSD 70,5% |
| 4P | ULSD 97,4% | JET A-1 97,4% | ULSD 85,0% |
| 4S | ULSD 97,4% | JET A-1 97,4% | ULSD 85,0% |
| 5P | ULSD 97,4% | JET A-1 97,4% | ULSD 80,0% |
| 5S | ULSD 97,4% | JET A-1 97,4% | ULSD 80,0% |

These findings are valid for the time and place of inspection only.

The certificate does not relieve the Vessel, Carrier and any other party from their contractual obligations and duties.

This certificate is electronically signed and stamped.

DATED: 27th of OCTOBER, 2023

For and on behalf of CISS GROUP Ukraine LLC
Registered Superintendent and Surveyor Member of FOSFA

