



Commodities International  
Shipping and Survey



FOSFA  
INTERNATIONAL

Page 1/2

CISS GROUP UKRAINE LLC  
member of CISS GROUP Pte.Ltd. (Singapore)  
5, Odessa Blv., Ovidiopol district,  
Lymanka village, Odessa region, 65037  
inspection@ciiss-group.com

CERTIFICATE No.: SGD01172

ORIGINAL

## TANK CLEANLINESS CERTIFICATE

In pursuance of an order received from our principal, requesting us to carry out inspection we hereby confirm as follows:

Description of goods:	CRUDE SUNFLOWER SEED OIL IN BULK
Vessel:	M/T METIN HUSEYNOV
Quantity:	5902,680 MT
B/L No. & Date:	NO. 1,2,3,4,5,6,7,8,9,10,11,12 DD 09.11.2023
Shipper:	SUNOLTA (SUISSE) SA RUE DU 23-JUIN 26, 2800 DELEMONT, SWITZERLAND REG.NO. CHE-345.676.000
Consignee:	TO ORDER
Notify address:	GOLDEN OIL FOR EXTRACTING, REFINING AND BOTTLING VEGETARIAN OILS. 6TH INDUSTRIAL ZONE ,6 OCTOBER CITY ,EL GIZA ,EGYPT.
Port of loading:	IZMAIL, UKRAINE
Port of discharge:	ANY EGYPTIAN MEDITERRANEAN PORT
Vessel Tanks Nos.:	COT 1, COT 2, COT 3, COT 4, COT 5, COT 6, COT 7, COT 8, COT 9, COT 10
Egyptian Importer Tax ID:	493903992
FOREIGN EXPORTER NAME:	Sunolta (Suisse) SA
Registration Type:	CHE-345.676.000 TVA
Registration Number:	CHE-345.676.000
Foreign Exporter ID:	CHE345676000TVA
Foreign Exporter Country:	SWITZERLAND
Foreign Exporter Country Code:	CH
ACID NO:	4939039922023110019, 4939039922023110027, 4939039922023110035, 4939039922023110050, 4939039922023110068, 4939039922023110076, 4939039922023110084, 4939039922023110092, 4939039922023110118, 4939039922023110126, 4939039922023110100, 4939039922023110043







**Commodities International  
Shipping and Survey**



**FOSFA  
INTERNATIONAL**

Page 2/2

**CISS GROUP UKRAINE LLC**  
member of CISS GROUP Pte.Ltd. (Singapore)  
5, Odessa Blv., Ovidiopol district,  
Lymanka village, Odessa region, 65037  
inspection@ciiss-group.com

**CERTIFICATE No.: SGD01172**

**ORIGINAL**

**RESULTS OF INSPECTION**

We hereby certify that prior to loading the ship's tanks, pumps and pipelines were visually inspected for cleanliness as far as possible and accessible: and were found empty, clean, free from harmful material and in this respect the ships tanks, pumps and pipes are suitable to receive and carry the oil. The last three cargoes as declared by the vessel are as follows:

SHIPS TANKS N°	LAST CARGO	SECOND LAST CARGO	THIRD LAST CARGO
1S	ULSD 10 PPM	RAPESEED OIL	ULSD 10 PPM
2P	ULSD 10 PPM	RAPESEED OIL	ULSD 10 PPM
3S	ULSD 10 PPM	RAPESEED OIL	ULSD 10 PPM
4P	ULSD 10 PPM	RAPESEED OIL	ULSD 10 PPM
5S	ULSD 10 PPM	RAPESEED OIL	ULSD 10 PPM
6P	ULSD 10 PPM	RAPESEED OIL	ULSD 10 PPM
7S	ULSD 10 PPM	RAPESEED OIL	ULSD 10 PPM
8P	ULSD 10 PPM	RAPESEED OIL	ULSD 10 PPM
9S	ULSD 10 PPM	RAPESEED OIL	ULSD 10 PPM
10P	ULSD 10 PPM	RAPESEED OIL	ULSD 10 PPM

These findings are valid for the time and place of inspection only.

The certificate does not relieve the Vessel, Carrier and any other party from their contractual obligations and duties.

**This certificate is electronically signed and stamped.**

**DATED: 9th of NOVEMBER, 2023**

**For and on behalf of CISS GROUP Ukraine LLC  
Registered Superintendent and Surveyor Member of FOSFA**

