



Commodities International  
Shipping and Survey



FOSFA  
INTERNATIONAL

CISS GROUP UKRAINE LLC  
member of CISS GROUP Pte.Ltd. (Singapore)  
5, Odessa Blv., Ovidiopol district,  
Lymanka village, Odessa region, 65037  
inspection@ciiss-group.com

Page 1/1

CERTIFICATE No.: SGD01204

ORIGINAL

## LAST THREE CARGOES CERTIFICATE

In pursuance of an order received from our principal, requesting us to carry out inspection we hereby confirm as follows:

Description of goods:	CRUDE SUNFLOWER SEED OIL IN BULK
Vessel:	M/T SES 1
Quantity:	2400,000 MT
B/L No. & Date:	NO. 1 AND 2 DD 14.12.2023
Shipper:	SUNOLTA (SUISSE) SA RUE DU 23-JUIN 26, 2800 DELEMONT, SWITZERLAND REG.NO. CHE-345.676.000
Consignee:	ELMAS FOR DEVELOPMENT CO. GIDA SANAYI A.S. 27620, BASPINAR 3. OSB, 83303 NOLU CADDE, NO.12, SEHITKAMIL, GAZIANTEP, TURKIYE
Notify address:	ELMAS FOR DEVELOPMENT CO. GIDA SANAYI A.S. 27620, BASPINAR 3. OSB, 83303 NOLU CADDE, NO.12, SEHITKAMIL, GAZIANTEP, TURKIYE
Port of loading:	ODESA, UKRAINE
Port of discharge:	WIMBA TERMINAL, ISKENDERUN PORT - TURKIYE
Vessel Tanks Nos.:	2P,3P,4P,5P,6P,7P,2S,3S,4S,5S,6S,7S,1C

### RESULTS OF INSPECTION

The last three cargoes as declared by the vessel are as follows:

SHIPS TANKS N°	LAST CARGO	SECOND LAST CARGO	THIRD LAST CARGO
1C	SFSO	CORN OIL	SFSO
2P	SFSO	CORN OIL	SFSO
2S	SFSO	CORN OIL	SFSO
3P	SFSO	CORN OIL	SFSO
3S	SFSO	CORN OIL	SFSO
4P	SFSO	CORN OIL	SFSO
4S	SFSO	CORN OIL	SFSO
5P	SFSO	CORN OIL	SFSO
5S	SFSO	CORN OIL	SFSO
6P	SFSO	CORN OIL	SFSO
6S	SFSO	CORN OIL	SFSO
7P	SFSO	CORN OIL	SFSO
7S	SFSO	CORN OIL	SFSO

These findings are valid for the time and place of inspection only.

The certificate does not relieve the Vessel, Carrier and any other party from their contractual obligations and duties.

This certificate is electronically signed and stamped.

DATED: 14th of DECEMBER, 2023

For and on behalf of CISS GROUP Ukraine LLC  
Registered Superintendent and Surveyor Member of FOSFA

