



Commodities International
Shipping and Survey



FOSFA
INTERNATIONAL

Page

1/1

CISS GROUP UKRAINE LLC

member of CISS GROUP Pte.Ltd. (Singapore)

5, Odessa Blv., Ovidiopol district,
Lymanka village, Odessa region, 65037
inspection@ciiss-group.com

CERTIFICATE No.: SGD01250

ORIGINAL

LAST THREE CARGOES CERTIFICATE

In pursuance of an order received from our principal, requesting us to carry out inspection we hereby confirm as follows:

Description of goods:

Vessel:

Quantity:

B/L No. & Date:

Shipper:

Consignee:

Notify address:

Port of loading:

Port of discharge:

Vessel Tanks Nos.:

UKRAINIAN ORIGIN, CRUDE SUNFLOWERSEED OIL, IN BULK

M/T BLUE CHEM

6500,000 MT

NO. 1 DD 11.02.2024

SUNOLTA (SUISSE) SA

RUE DU 23-JUIN 26,

2800 DELEMONT, SWITZERLAND

TO THE ORDER OF SUNAR PAZARLAMA

VE DIS TIC LTD STI KOZYATAGI MAH.CARDAK

SOK.HERTI PLAZA NO:1,IC KAPI NO:3

KADIKOY,ISTANBUL /TURKIYE

TAX REG OFFICE:ERENKOY,

TAX REG NO:2010 3027 38

SUNAR PAZARLAMA VE DIS TIC LTD STI

KOZYATAGI MAH.CARDAK SOK.HERTI PLAZA

NO:1,IC KAPI NO:3 KADIKOY,

ISTANBUL /TURKIYE

TAX REG OFFICE:ERENKOY,

TAX REG NO:2010 3027 38

ODESA, UKRAINE

MERSIN (MIP OR SAVKA) OR ISKENDERUN PORT / TURKIYE

1P,2P,3P,4P,5P,6P,1S,2S,3S,4S,5S,6S.

RESULTS OF INSPECTION

The last three cargoes as declared by the vessel are as follows:

Ships Tanks N°	Last cargo	Second Last Cargo	Third Last Cargo
1P	SUNFLOWER OIL (85.3%)	ULSD 10PPM (89.5 %)	ULSD 10PPM (96.1 %)
1S	SUNFLOWER OIL (85.2%)	ULSD 10PPM (89.6 %)	ULSD 10PPM (96.2 %)
2P	SUNFLOWER OIL (86.2%)	ULSD 10PPM (89.5 %)	ULSD 10PPM (96.1 %)
2S	SUNFLOWER OIL (86.2%)	ULSD 10PPM (89.5 %)	ULSD 10PPM (96.0 %)
3P	SUNFLOWER OIL (88.9%)	ULSD 10PPM (88.9 %)	ULSD 10PPM (96.7 %)
3S	SUNFLOWER OIL (86.5%)	ULSD 10PPM (87.4 %)	ULSD 10PPM (96.3 %)
4P	SUNFLOWER OIL (87.4%)	ULSD 10PPM (84.1 %)	ULSD 10PPM (80.4 %)
4S	SUNFLOWER OIL (83.6%)	ULSD 10PPM (83.8 %)	ULSD 10PPM (81.1 %)
5P	SUNFLOWER OIL (84.0%)	ULSD 10PPM (75.3 %)	ULSD 10PPM (96.2 %)
5S	SUNFLOWER OIL (86.0%)	ULSD 10PPM (76.4 %)	ULSD 10PPM (96.5 %)
6P	SUNFLOWER OIL (74.0%)	ULSD 10PPM (70.6 %)	ULSD 10PPM (95.8 %)
6S	SUNFLOWER OIL (74.2%)	ULSD 10PPM (70.8 %)	ULSD 10PPM (95.6 %)

These findings are valid for the time and place of inspection only.

The certificate does not relieve the Vessel, Carrier and any other party from their contractual obligations and duties.

This certificate is electronically signed and stamped.

DATED: 11th of FEBRUARY, 2024

For and on behalf of CISS GROUP Ukraine LLC
Registered Superintendent and Surveyor Member of FOSFA

