



Commodities International
Shipping and Survey



FOSFA
INTERNATIONAL

Page

1/1

CISS GROUP UKRAINE LLC
member of CISS GROUP Pte.Ltd. (Singapore)
5, Odessa Blv., Ovidiopol district,
Lymanka village, Odessa region, 65037
inspection@ciiss-group.com

CERTIFICATE No.: SGD01250

ORIGINAL

TANK CLEANLINESS CERTIFICATE

In pursuance of an order received from our principal, requesting us to carry out inspection we hereby confirm as follows:

Description of goods: UKRAINIAN ORIGIN, CRUDE SUNFLOWERSEED OIL, IN BULK
Vessel: M/T BLUE CHEM
Quantity: 6500,000 MT
B/L No. & Date: NO. 1 DD 11.02.2024
Shipper: SUNOLTA (SUISSE) SA
RUE DU 23-JUIN 26,
2800 DELEMONT, SWITZERLAND
Consignee: TO THE ORDER OF SUNAR PAZARLAMA
VE DIS TIC LTD STI KOZYATAGI MAH.CARDAK
SOK.HERTI PLAZA NO:1,IC KAPI NO:3
KADIKOY,ISTANBUL /TURKIYE
TAX REG OFFICE:ERENKOY,
TAX REG NO:2010 3027 38
Notify address: SUNAR PAZARLAMA VE DIS TIC LTD STI
KOZYATAGI MAH.CARDAK SOK.HERTI PLAZA
NO:1,IC KAPI NO:3 KADIKOY,
ISTANBUL /TURKIYE
TAX REG OFFICE:ERENKOY,
TAX REG NO:2010 3027 38
Port of loading: ODESA, UKRAINE
Port of discharge: MERSIN (MIP OR SAVKA) OR ISKENDERUN PORT / TURKIYE
Vessel Tanks Nos.: 1P,2P,3P,4P,5P,6P,1S,2S,3S,4S,5S,6S.

RESULTS OF INSPECTION

We hereby certify that prior to loading the ship's tanks, pumps and pipelines were visually inspected for cleanliness as far as possible and accessible: and were found empty, clean, free from harmful material and in this respect the ships tanks, pumps and pipes are suitable to receive and carry the oil. The last three cargoes as declared by the vessel are as follows:

Ships Tanks N°	Last cargo	Second Last Cargo	Third Last Cargo
1P	SUNFLOWER OIL (85.3%)	ULSD 10PPM (89.5 %)	ULSD 10PPM (96.1 %)
1S	SUNFLOWER OIL (85.2%)	ULSD 10PPM (89.6 %)	ULSD 10PPM (96.2 %)
2P	SUNFLOWER OIL (86.2%)	ULSD 10PPM (89.5 %)	ULSD 10PPM (96.1 %)
2S	SUNFLOWER OIL (86.2%)	ULSD 10PPM (89.5 %)	ULSD 10PPM (96.0 %)
3P	SUNFLOWER OIL (88.9%)	ULSD 10PPM (88.9 %)	ULSD 10PPM (96.7 %)
3S	SUNFLOWER OIL (86.5%)	ULSD 10PPM (87.4 %)	ULSD 10PPM (96.3 %)
4P	SUNFLOWER OIL (87.4%)	ULSD 10PPM (84.1 %)	ULSD 10PPM (80.4 %)
4S	SUNFLOWER OIL (83.6%)	ULSD 10PPM (83.8 %)	ULSD 10PPM (81.1 %)
5P	SUNFLOWER OIL (84.0%)	ULSD 10PPM (75.3 %)	ULSD 10PPM (96.2 %)
5S	SUNFLOWER OIL (86.0%)	ULSD 10PPM (76.4 %)	ULSD 10PPM (96.5 %)
6P	SUNFLOWER OIL (74.0%)	ULSD 10PPM (70.6 %)	ULSD 10PPM (95.8 %)
6S	SUNFLOWER OIL (74.2%)	ULSD 10PPM (70.8 %)	ULSD 10PPM (95.6 %)

These findings are valid for the time and place of inspection only.

The certificate does not relieve the Vessel, Carrier and any other party from their contractual obligations and duties.

This certificate is electronically signed and stamped.

DATED: 11th of FEBRUARY, 2024

For and on behalf of CISS GROUP Ukraine LLC
Registered Superintendent and Surveyor Member of FOSFA

