



Commodities International
Shipping and Survey



FOSFA
INTERNATIONAL

Page

1/2

CISS GROUP UKRAINE LLC
member of CISS GROUP Pte.Ltd. (Singapore)
5, Odessa Blv., Ovidiopol district,
Lymanka village, Odessa region, 65037
inspection@ciiss-group.com

CERTIFICATE No.: SGD01262

ORIGINAL

TANK INSPECTION CERTIFICATE

In pursuance of an order received from our principal, requesting us to carry out inspection we hereby confirm as follows:

Description of goods:	CRUDE SUNFLOWER SEED OIL UKRAINE ORIGIN, IN BULK FOR FOOD USE AFTER APPROPRIATE REFINING
Vessel:	M/T VITIS
Quantity:	5900,000 MT
B/L No. & Date:	NO. 1 DD 15.03.2024
Shipper:	SUNOLTA OU HARJU MAAKOND, TALLINN, KESKLINNA LINNAOSA, JOE TN 4C, 10151, ESTONIA
Consignee:	TO THE ORDER
Notify address:	CASA OLEARIA ITALIANA S.P.A VIA BAIONE 200 70043 MONOPOLI (BARI)
Port of loading:	ODESA, UKRAINE
Port of discharge:	MONOPOLI, ITALY
Vessel Tanks Nos.:	1P,2P,3P,4P,5P,6P,7P,8P,9P,10P,11P, 1S,2S,3S,4S,5S,6S,7S,8S,9S,10S,11S

RESULTS OF INSPECTION

We hereby certify that prior to loading the ship's tanks, pumps and pipelines were visually inspected for cleanliness as far as possible and accessible: and were found empty, clean, free from harmful material and in this respect the ships tanks, pumps and pipes are suitable to receive and carry the oil. The last three cargoes as declared by the vessel are as follows:

SHIPS TANKS N°	LAST CARGO	SECOND LAST CARGO	THIRD LAST CARGO
1P	SFSO (98%)	SFSO (98%)	SFSO (98%)
1S	SFSO (98%)	SFSO (98%)	SFSO (98%)
2P	SFSO (98%)	SFSO (98%)	SFSO (98%)
2S	SFSO (98%)	SFSO (98%)	SFSO (98%)
3P	SFSO (98%)	SFSO (98%)	SFSO (98%)
3S	SFSO (98%)	SFSO (98%)	SFSO (98%)
4P	SFSO (98%)	SFSO (98%)	SFSO (98%)
4S	SFSO (98%)	SFSO (98%)	SFSO (98%)
5P	SFSO (98%)	SFSO (98%)	SFSO (98%)
5S	SFSO (98%)	SFSO (98%)	SFSO (98%)





**Commodities International
Shipping and Survey**



**FOSFA
INTERNATIONAL**

Page 2/2

CISS GROUP UKRAINE LLC
member of **CISS GROUP Pte.Ltd. (Singapore)**
5, Odessa Blv., Ovidiopol district,
Lymanka village, Odessa region, 65037
inspection@ciiss-group.com

CERTIFICATE No.: SGD01262

ORIGINAL

6P	SFSO (98%)	SFSO (98%)	SFSO (98%)
6S	SFSO (98%)	SFSO (98%)	SFSO (98%)
7P	SFSO (98%)	SFSO (98%)	SFSO (98%)
7S	SFSO (98%)	SFSO (98%)	SFSO (98%)
8P	SFSO (96%)	SFSO (98%)	SFSO (98%)
8S	SFSO (96%)	SFSO (98%)	SFSO (98%)
9P	SFSO (98%)	SFSO (98%)	SFSO (98%)
9S	SFSO (98%)	SFSO (98%)	SFSO (98%)
10P	SFSO (98%)	SFSO (98%)	SFSO (98%)
10S	SFSO (98%)	SFSO (98%)	SFSO (98%)
11P	SFSO (94%)	SFSO (96%)	SFSO (94%)
11S	SFSO (94%)	SFSO (95%)	SFSO (94%)

These findings are valid for the time and place of inspection only.
The certificate does not relieve the Vessel, Carrier and any other party from their contractual obligations and duties.

This certificate is electronically signed and stamped.

DATED: 15th of MARCH, 2024

For and on behalf of CISS GROUP Ukraine LLC
Registered Superintendent and Surveyor Member of FOSFA



This certificate is issued to any job or services carried out within the GENERAL TERMS AND CONDITION OF BUSINESS printed overleaf. This certificate is not intended to relieve the parties of any relevant sales contract from their contractual obligations. The Company's responsibility under this Certificate is limited to proven negligence and will in no case be more than ten times the amount of the fees.