

## Commodities International Shipping and Survey







Page

1/1

CISS GROUP UKRAINE LLC member of CISS GROUP Pte.Ltd. (Singapore) 5, Odessa Blv., Ovidiopol district, Lymanka village, Odessa region, 65037 inspection@ciss-group.com

**CERTIFICATE No.: SGD01270** 

**ORIGINAL** 

## **ORIGINAL CERTIFICATE OF LAST THREE CARGOES**

In pursuance of an order received from our principal, requesting us to carry out inspection we

hereby confirm as follows:

Description of goods: CRUDE SUNFLOWER OIL OBTAINED FROM SUNFLOWER SEEDS

Vessel: M/T ELIANA Quantity: 5250,000 MT

B/L No. & Date: NO. 1 AND 2 DD 11.03.2024

Shipper: SUNOLTA OU

HARJU MAAKOND, TALLINN, KESKLINNA LINNAOSA, JOE TN 4C, 10151 ESTONIA

Consignee: TO ORDER
Notify address: AGRIMED S.A.

ZONE INDUSTRIELLE AGAREB 3030 SFAX, TUNISIA

Port of loading: ODESA, UKRAINE
Port of discharge: SFAX PORT, TUNISIA

Vessel Tanks Nos.: 1P,2P,3P,4P,5P,1S,2S,3S,4S,5S

## **RESULTS OF INSPECTION**

The last three cargoes as declared by the vessel are as follows:

SHIPS TANKS N°	LAST CARGO	SECOND LAST CARGO	THIRD LAST CARGO
1P	SFSO (94.18%)	SFSO (92.02%)	SFSO (94.91%)
15	SFSO (91.06%)	SFSO (92.46%)	SFSO (94.85%)
2P	SFSO (90.89%)	SFSO (92.97%)	SFSO (93.00%)
28	SFSO (92.19%)	SFSO (92.91%)	SFSO (94.44%)
3P	SFSO (89.42%)	SFSO (85.21%)	SFSO (94.58%)
3S	SFSO (84.37%)	SFSO (85.33%)	SFSO (94.58%)
4P cas cas cas cas	SFSO (93.06%)	SFSO (86.83%)	SFSO (81.12%)
45° CRS	SFSO (81.47%)	SFSO (85.63%)	SFSO (84.46%)
5P. Com Come Come Come	SFSO (91.59%)	SFSO (87.97%)	SFSO (80.59%)
5S case case case case	SFSO (76.91%)	SFSO (85.55%)	SFSO (79.87%)

These findings are valid for the time and place of inspection only.

The certificate does not relieve the Vessel, Carrier and any other party from their contractual obligations and duties.

This certificate is electronically signed and stamped.



DATED: 11th of MARCH, 2024
For and on behalf of CISS GROUP Ukraine LLC
Registered Superintendent and Surveyor Member of FOSFA



