



Commodities International
Shipping and Survey



FOSFA
INTERNATIONAL

Page 1/2

CISS GROUP UKRAINE LLC
member of CISS GROUP Pte.Ltd. (Singapore)
5, Odessa Blv., Ovidiopol district,
Lymanka village, Odessa region, 65037
inspection@ciiss-group.com

CERTIFICATE No.: SGD01270

ORIGINAL

ORIGINAL INSPECTION CERTIFICATE

In pursuance of an order received from our principal, requesting us to carry out inspection we hereby confirm as follows

Description of goods:	CRUDE SUNFLOWER OIL OBTAINED FROM SUNFLOWER SEEDS
Vessel:	M/T ELIANA
Quantity:	5250,000 MT
B/L No. & Date:	NO. 1 AND 2 DD 11.03.2024
Shipper:	SUNOLTA OU HARJU MAAKOND, TALLINN, KESKLINNA LINNAOSA, JOE TN 4C, 10151 ESTONIA
Consignee:	TO ORDER
Notify address:	AGRIMED S.A. ZONE INDUSTRIELLE AGAREB 3030 SFAX, TUNISIA
Port of loading:	ODESA, UKRAINE
Port of discharge:	SFAX PORT, TUNISIA
Vessel Tanks Nos.:	1P,2P,3P,4P,5P,1S,2S,3S,4S,5S

RESULTS OF INSPECTION

We hereby certify that prior to loading the ship's tanks, pumps and pipelines were visually inspected for cleanliness as far as possible and accessible: and were found empty, clean, free from harmful material and in this respect the ships tanks, pumps and pipes are suitable to receive and carry the oil. The last three cargoes as declared by the vessel are as follows:

SHIPS TANKS N°	LAST CARGO	SECOND LAST CARGO	THIRD LAST CARGO
1P	SFSO (94.18%)	SFSO (92.02%)	SFSO (94.91%)
1S	SFSO (91.06%)	SFSO (92.46%)	SFSO (94.85%)
2P	SFSO (90.89%)	SFSO (92.97%)	SFSO (93.00%)
2S	SFSO (92.19%)	SFSO (92.91%)	SFSO (94.44%)
3P	SFSO (89.42%)	SFSO (85.21%)	SFSO (94.58%)
3S	SFSO (84.37%)	SFSO (85.33%)	SFSO (94.58%)
4P	SFSO (93.06%)	SFSO (86.83%)	SFSO (81.12%)
4S	SFSO (81.47%)	SFSO (85.63%)	SFSO (84.46%)
5P	SFSO (91.59%)	SFSO (87.97%)	SFSO (80.59%)
5S	SFSO (76.91%)	SFSO (85.55%)	SFSO (79.87%)





**Commodities International
Shipping and Survey**



**FOSFA
INTERNATIONAL**

Page 2/2

CISS GROUP UKRAINE LLC
member of **CISS GROUP Pte.Ltd. (Singapore)**
5, Odessa Blv., Ovidiopol district,
Lymanka village, Odessa region, 65037
inspection@ciiss-group.com

CERTIFICATE No.: SGD01270

ORIGINAL

ULLAGE REPORT OF SHIP'S TANKS

TANK	OBS	CORRECT.	TOTAL OBS	TEMP	DENSITY	CORRECTION FOR THERMAL EXPANSION	GROSS
NR	ULLAGE	ULLAGE	VOLUME	IN	AT OBS		WEIGHT
	CM	CM	M3	C	TEMP		MT
1P	181,5	184,8	316,704	17,0	0,92254	1,000066	292,191
1S	181,0	184,3	317,645	17,4	0,92227	1,000079	292,978
2P	199,5	203,9	652,194	18,1	0,92179	1,000102	601,247
2S	189,0	193,4	660,558	18,6	0,92145	1,000119	608,744
3P	204,0	208,4	685,563	16,8	0,92268	1,000059	632,593
3S	311,5	315,9	587,347	17,4	0,92227	1,000079	541,735
4P	221,0	225,4	672,575	19,0	0,92118	1,000132	619,644
4S	233,5	237,9	660,800	19,3	0,92098	1,000142	608,670
5P	210,0	214,3	602,869	17,9	0,92193	1,000096	555,856
5S	300,0	304,3	523,406	17,8	0,92200	1,000092	482,625
							5236,283
METRIC TONNES AIR LOADED VEF NOT APPLIED:					5236,283	DENSITY AT 20°C	0,92050
V.E.F					0,9984		
METRIC TONNES AIR LOADED VEF APPLIED:					5244,674		
				DRAFT:	FORE	5,85	TRIM: 0,65
					AFT:	6,50	LIST: NIL

These findings are valid for the time and place of inspection only.
The certificate does not relieve the Vessel, Carrier and any other party from their contractual obligations and duties.

This certificate is electronically signed and stamped.

DATED: 11th of MARCH, 2024

For and on behalf of CISS GROUP Ukraine LLC
Registered Superintendent and Surveyor Member of FOSFA



This certificate is issued to any job or services carried out within the GENERAL TERMS AND CONDITION OF BUSINESS printed overleaf. This certificate is not intended to relieve the parties of any relevant sales contract from their contractual obligations. The Company's responsibility under this Certificate is limited to proven negligence and will in no case be more than ten times the amount of the fees.