







CISS GROUP UKRAINE LLC member of CISS GROUP Pte.Ltd. (Singapore) 5, Odessa Blv., Ovidiopol district, Lymanka village, Odessa region, 65037 inspection@ciss-group.com

CERTIFICATE No.: SGD01280

ORIGINAL

VESSEL'S DRY AND CLEAN TANKS CERTIFICATE

In pursuance of an order received from our principal, requesting us to carry out inspection we hereby confirm as follows:

Description of goods: CRUDE SUNFLOWERSEED OIL

Vessel: M/T BARBAROS HAYRETTIN VARDAL

Quantity: 5400,000 MT

B/L No. & Date: NO. 1 DD 21.03.2024 Shipper: SUNOLTA (SUISSE) SA RUE DU 23-JUIN 26,

2800 DELEMONT, SWITZERLAND

Consignee: TO THE ORDER

Notify address: MIGASA ACEITES S.L.U. CARRETERA

MADRID - CADIZ KM 556 41703 DOS

HERMANAS. SEVILLA. SPAIN

Port of loading: ODESA, UKRAINE Port of discharge: SEVILLE, SPAIN

Vessel Tanks Nos.: 1P,2P,3P,4P,5P,1S,2S,3S,4S,5S

RESULTS OF INSPECTION

The last three cargoes as declared by the vessel are as follows:

SHIPS TANKS N°	LAST CARGO	SECOND LAST CARGO	THIRD LAST CARGO
1P	VEGOIL %95	VEGOIL %88	Caustic Soda Solution %73
1S	VEGOIL %95	VEGOIL %88	Caustic Soda Solution %72
2P	VEGOIL %95	VEGOIL %95	Caustic Soda Solution %84
2S	VEGOIL %95	VEGOIL %95	Caustic Soda Solution %85
3P	VEGOIL %95	VEGOIL %95	Caustic Soda Solution %80
3S	VEGOIL %95	VEGOIL %95	Caustic Soda Solution %80
4P	VEGOIL %93	VEGOIL %93	Caustic Soda Solution %71
4S cas clas clas clas clas cas cas	VEGOIL %93	VEGOIL %89	Caustic Soda Solution %71
5P Clear Cle	VEGOIL %73	VEGOIL %81	Caustic Soda Solution %60
5S CREE CREE CREE CREE CREE	VEGOIL %80	VEGOIL %86	Caustic Soda Solution %60

These findings are valid for the time and place of inspection only.

The certificate does not relieve the Vessel, Carrier and any other party from their contractual obligations and duties.

This certificate is electronically signed and stamped.

DATED: 21st of MARCH, 2024

For and on behalf of CISS GROUP Ukraine LLC

Registered Superintendent and Surveyor Member of FOSFA





