



Commodities International
Shipping and Survey



CISS GROUP UKRAINE LLC
member of CISS GROUP Pte.Ltd. (Singapore)
5, Odessa Blv., Ovidiopol district,
Lymanka village, Odessa region, 65037
inspection@ciiss-group.com

Page 1/1

CERTIFICATE No.: SGD01297

ORIGINAL

LAST THREE CARGOES CERTIFICATE

In pursuance of an order received from our principal, requesting us to carry out inspection we hereby confirm as follows:

Description of goods:	UKRAINIAN ORIGIN CRUDE SUNFLOWERSEED OIL, IN BULK
Vessel:	M/T ELIANA
Quantity:	5250,000 MT
B/L No. & Date:	NO. 1 DD 08.04.2024
Shipper:	SUNOLTA (SUISSE) SA RUE DU 23-JUIN 26, 2800 DELEMONT, SWITZERLAND
Consignee:	TO ORDER
Notify address:	BUNGE GIDA SAN. VE TIC. A.S. CENTRUM IS MERKEZI AYDINEVLER SANAYI CAD. NO:3 / 301 34854 – KUCUKYALI – MALTEPE ISTANBUL – TURKEY
Port of loading:	ODESA, UKRAINE
Port of discharge:	TEKIRDAG PORT OF TURKEY
Vessel Tanks Nos.:	1P, 2P, 3P, 4P, 5P, 1S, 2S, 3S, 4S, 5S.

RESULTS OF INSPECTION

The last three cargoes as declared by the vessel are as follows:

SHIPS TANKS N°	LAST CARGO	SECOND LAST CARGO	THIRD LAST CARGO
1P	ULSD (96.87%)	SFSO (93.44%)	SFSO (94.18%)
1S	ULSD (96.65%)	SFSO (93.25%)	SFSO (91.06%)
2P	ULSD (97.32%)	SFSO (91.93%)	SFSO (90.89%)
2S	ULSD (97.37%)	SFSO (93.11%)	SFSO (92.19%)
3P	ULSD (97.45%)	SFSO (91.51%)	SFSO (89.42%)
3S	ULSD (96.60%)	SFSO (78.40%)	SFSO (84.37%)
4P	ULSD (97.57%)	SFSO (89.79%)	SFSO (93.06%)
4S	ULSD (95.96%)	SFSO (88.22%)	SFSO (81.47%)
5P	ULSD (97.13%)	SFSO (90.65%)	SFSO (91.59%)
5S	ULSD (96.85%)	SFSO (78.64%)	SFSO (76.91%)

These findings are valid for the time and place of inspection only.

The certificate does not relieve the Vessel, Carrier and any other party from their contractual obligations and duties.

This certificate is electronically signed and stamped.

DATED: 08th of APRIL, 2024

For and on behalf of CISS GROUP Ukraine LLC
Registered Superintendent and Surveyor Member of FOSFA

