



Commodities International
Shipping and Survey



CISS GROUP UKRAINE LLC
member of CISS GROUP Pte.Ltd. (Singapore)
5, Odessa Blv., Ovidiopol district,
Lymanka village, Odessa region, 65037
inspection@ciiss-group.com

Page 1/1

CERTIFICATE No.: SGD01297

ORIGINAL

TANK CLEANLINESS CERTIFICATE

In pursuance of an order received from our principal, requesting us to carry out inspection we hereby confirm as follows:

| | |
|-----------------------|---|
| Description of goods: | UKRAINIAN ORIGIN CRUDE SUNFLOWERSEED OIL, IN BULK |
| Vessel: | M/T ELIANA |
| Quantity: | 5250,000 MT |
| B/L No. & Date: | NO. 1 DD 08.04.2024 |
| Shipper: | SUNOLTA (SUISSE) SA RUE DU 23-JUIN 26, 2800 DELEMONT, SWITZERLAND |
| Consignee: | TO ORDER |
| Notify address: | BUNGE GIDA SAN. VE TIC. A.S. CENTRUM IS MERKEZI AYDINEVLER SANAYI CAD. NO:3 / 301 34854 – KUCUKYALI – MALTEPE ISTANBUL – TURKEY |
| Port of loading: | ODESA, UKRAINE |
| Port of discharge: | TEKIRDAG PORT OF TURKEY |
| Vessel Tanks Nos.: | 1P,2P,3P,4P,5P,1S, 2S, 3S, 4S, 5S. |

RESULTS OF INSPECTION

We hereby certify that prior to loading the ship's tanks, pumps and pipelines were visually inspected for cleanliness as far as possible and accessible: and were found empty, clean, free from harmful material and in this respect the ships tanks, pumps and pipes are suitable to receive and carry the oil. The last three cargoes as declared by the vessel are as follows:

| SHIPS TANKS N° | LAST CARGO | SECOND LAST CARGO | THIRD LAST CARGO |
|-------------------|---------------|-------------------|------------------|
| 1P | ULSD (96.87%) | SFSO (93.44%) | SFSO (94.18%) |
| 1S | ULSD (96.65%) | SFSO (93.25%) | SFSO (91.06%) |
| 2P | ULSD (97.32%) | SFSO (91.93%) | SFSO (90.89%) |
| 2S | ULSD (97.37%) | SFSO (93.11%) | SFSO (92.19%) |
| 3P | ULSD (97.45%) | SFSO (91.51%) | SFSO (89.42%) |
| 3S | ULSD (96.60%) | SFSO (78.40%) | SFSO (84.37%) |
| 4P | ULSD (97.57%) | SFSO (89.79%) | SFSO (93.06%) |
| 4S | ULSD (95.96%) | SFSO (88.22%) | SFSO (81.47%) |
| 5P | ULSD (97.13%) | SFSO (90.65%) | SFSO (91.59%) |
| 5S | ULSD (96.85%) | SFSO (78.64%) | SFSO (76.91%) |

These findings are valid for the time and place of inspection only.
The certificate does not relieve the Vessel, Carrier and any other party from their contractual obligations and duties.

This certificate is electronically signed and stamped.

DATED: 08th of APRIL, 2024

For and on behalf of CISS GROUP Ukraine LLC
Registered Superintendent and Surveyor Member of FOSFA

