







CISS GROUP UKRAINE LLC
member of CISS GROUP Pte.Ltd. (Singapore)

5, Odessa Blv., Ovidiopol district, Lymanka village, Odessa region, 65037 inspection@ciss-group.com **CERTIFICATE No.: SGD01310** 

**ORIGINAL** 

## FOSFA TANKS CLEANLINESS INSPECTION CERTIFICATE

In pursuance of an order received from our principal, requesting us to carry out inspection we

hereby confirm as follows:

Description of goods: STANDARD CRUDE SUNFLOWERSEED OIL,

UKRAINIAN OR EU ANY ORIGIN LOADED AT EU PORT

Vessel: M/T BARBAROS ULUC VARDAL

Quantity: 5200,000 MT

B/L No. & Date: NO. 1 DD 24.04.2024

Shipper: SUNOLTA OU

HARJU MAAKOND, TALLINN, KESKLINNA LINNAOSA, JOE TN 4C, 10151 ESTONIA

Consignee: F.J. SANCHEZ SUCESORES, SAU,

C/ CAMPANARIO S/N.

04270, SORBAS, ALMERIA, ESPANA

Notify address: F.J. SANCHEZ SUCESORES, SAU,

C/ CAMPANARIO S/N,

04270, SORBAS, ALMERIA, ESPANA

Port of loading: ODESA, UKRAINE

Port of discharge: CARBONERAS, ALMERIA, SPAIN Vessel Tanks Nos.: 1P,2P,3P,4P,5P,1S,2S,3S,45,5S.

## **RESULTS OF INSPECTION**

We hereby certify that prior to loading the ship's tanks, pumps and pipelines were visually inspected for cleanliness as far as possible and accessible: and were found empty, clean, free from harmful material and in this respect the ships tanks, pumps and pipes are suitable to receive and carry the oil. The last three cargoes as declared by the vessel are as follows:

SHIPS TANKS N°	LAST CARGO	SECOND LAST CARGO	THIRD LAST CARGO
1P	SUNFLOWER SEED OIL %92	SUNFLOWER SEED OIL %93	MOLASSES %67
1S	SUNFLOWER SEED OIL %93	SUNFLOWER SEED OIL %93	MOLASSES %67
2P	SUNFLOWER SEED OIL %93	SUNFLOWER SEED OIL %93	CRUDE SUNFLOWER SEED OIL %93
2S	SUNFLOWER SEED OIL %93	SUNFLOWER SEED OIL %94	CRUDE SUNFLOWER SEED OIL %93
3P	SUNFLOWER SEED OIL %92	SUNFLOWER SEED OIL %92	CRUDE SUNFLOWER SEED OIL %91
38	SUNFLOWER SEED OIL %93	SUNFLOWER SEED OIL %93	CRUDE SUNFLOWER SEED OIL %91
4P	SUNFLOWER SEED OIL %86	SUNFLOWER SEED OIL %87	MOLASSES %65
48	SUNFLOWER SEED OIL %87	SUNFLOWER SEED OIL %85	MOLASSES %65
5P	SUNFLOWER SEED OIL %80	SUNFLOWER SEED OIL %79	HOSSO %76
5S	SUNFLOWER SEED OIL %80	SUNFLOWER SEED OIL %78	HOSSO %73

These findings are valid for the time and place of inspection only.

The certificate does not relieve the Vessel, Carrier and any other party from their contractual obligations and duties.

This certificate is electronically signed and stamped.

DATED: 24th of APRIL, 2024
For and on behalf of CISS GROUP Ukraine LLC
Registered Superintendent and Surveyor Member of FOSFA





