



CISS GROUP UKRAINE LLC
member of CISS GROUP Pte.Ltd. (Singapore)
5, Odessa Blv., Ovidiopol district,
Lymanka village, Odessa region, 65037
inspection@ciis-group.com

CERTIFICATE No.: SGD01335

ORIGINAL

CERTIFICATE OF CLEANLINESS SHIP'S TANK

In pursuance of an order received from our principal, requesting us to carry out inspection we hereby confirm as follows:

Description of goods:	CRUDE SUNFLOWER SEED OIL UKRAINE ORIGIN, IN BULK FOR FOOD USE AFTER APPROPRIATE REFINING
Vessel:	M/T VEYSEL VARDAL
Quantity:	3000,000 MT
B/L No. & Date:	NO. 1 DD 07 08.2024
Shipper:	SUNOLTA (SUISSE) SA RUE DU 23-JUIN 26, 2800 DELEMONT, SWITZERLAND
Consignee:	TO THE ORDER
Notify address:	CASA OLEARIA ITALIANA S.P.A VIA BAIONE 200 70043 MONOPOLI (BARI)
Port of loading:	ODESA, UKRAINE
Port of discharge:	MONOPOLI, ITALY
Vessel Tanks Nos.:	1C, 2C, 3C, 4C, 5C

RESULTS OF INSPECTION

We hereby certify that prior to loading the ship's tanks, pumps and pipelines were visually inspected for cleanliness as far as possible and accessible and were found empty, clean, free from harmful material and in this respect the ship's tanks, pumps and pipes are suitable to receive and carry the oil. The last three cargoes as declared by the vessel are as follows:

Ships Tanks N°	Last cargo	Second Last Cargo	Third Last Cargo
1C	SUNFLOWER SEED OIL %96	SUNFLOWER SEED OIL %96	SUNFLOWER SEED OIL %96
2C	BEET MOLASSES %82	SUNFLOWER SEED OIL %96	C DEGUMED CORN OIL %95.3
3C	HIGHT INVERT BEET MOLASSES %77	SUNFLOWER SEED OIL %97	C. DEGUMED CORN OIL %96
4C	BEET MOLASSES %823	SUNFLOWER SEED OIL %97	C. DEGUMED CORN OIL %95.3
5C	HIGHT INVERT BEET MOLASSES %60	SUNFLOWER SEED OIL %96	C. DEGUMED CORN OIL %95.5

These findings are valid for the time and place of inspection only.

The certificate does not relieve the Vessel, Carrier and any other party from their contractual obligations and duties.

DATED: 7th of AUGUST, 2024

For and on behalf of CISS GROUP Ukraine LLC
Registered Superintendent and Surveyor Member of FOSFA

