



Commodities International
Shipping and Survey



FOSFA
INTERNATIONAL

Page

1/1

CISS GROUP UKRAINE LLC
member of CISS GROUP Pte.Ltd. (Singapore)
5, Odessa Blv., Ovidiopol district,
Lymanka village, Odessa region, 65037
inspection@ciiss-group.com

CERTIFICATE No.: SGD01359

ORIGINAL

LAST THREE CARGOES CERTIFICATE

In pursuance of an order received from our principal, requesting us to carry out inspection we hereby confirm as follows:

Description of goods:	UKRAINIAN CRUDE SUNFLOWERSEED OIL, IN BULK
Vessel:	M/T HIRA V
Quantity:	6118,430 MT
B/L No. & Date:	NO. 1 AND 2 DD 20.08.2024
Shipper:	SUNOLTA (SUISSE) SA RUE DU 23-JUIN 26, 2800 DELEMONT, SWITZERLAND
Consignee:	TO ORDER
Notify address:	BUNGE ITALIA SPA VIA BAIONA, 203 RAVENNA, ITALY
Port of loading:	ODESA, UKRAINE
Port of discharge:	RAVENNA, ITALY
Vessel Tanks Nos.:	1P, 2P, 3P, 4P, 5P, 6P, 1S, 2S, 3S, 4S, 5S, 6S

RESULTS OF INSPECTION

The last three cargoes as declared by the vessel are as follows:

SHIPS TANKS N°	LAST CARGO	SECOND LAST CARGO	THIRD LAST CARGO
1P	MTBE 95.6%	CSBO 95.5%	CSBO 95.5%
1S	MTBE 96.3%	CSBO 95.5%	CSBO 95.5%
2P	MTBE 96.9%	CSBO 96.6%	CSBO 96.6%
2S	MTBE 96.4%	CSBO 96.1%	CSBO 96.1%
3P	MTBE 96.9%	CSBO 95.3%	CSBO 95.3%
3S	MTBE 97.2%	CSBO 95.8%	CSBO 95.8%
4P	MTBE 96.8%	CSBO 95.5%	CSBO 93.7%
4S	MTBE 95.8%	CSBO 94.6%	CSBO 92.8%
5P	MTBE 96.8%	CSBO 95.1%	CSBO 93.3%
5S	MTBE 97.2%	CSBO 95.5%	CSBO 93.7%
6P	MTBE 96.9%	CSBO 75.0%	CSBO 71.5%
6S	MTBE 97.0%	CSBO 75.1%	CSBO 71.6%

These findings are valid for the time and place of inspection only.

The certificate does not relieve the Vessel, Carrier and any other party from their contractual obligations and duties.

This certificate is electronically signed and stamped.

DATED: 20th of AUGUST, 2024

For and on behalf of CISS GROUP Ukraine LLC
Registered Superintendent and Surveyor Member of FOSFA

