





CISS GROUP UKRAINE LLC member of CISS GROUP Pte.Ltd. (Singapore) 5, Odessa Blv., Ovidiopol district, Lymanka village, Odessa region, 65037 inspection@ciss-group.com

1/1

**CERTIFICATE No.: SGD01372** 

**ORIGINAL** 

## **LAST 3 CARGOES CERTIFICATE**

In pursuance of an order received from our principal, requesting us to carry out inspection we hereby confirm as follows:

Description of goods: UKRAINIAN ORIGIN CRUDE SUNFLOWER OIL,

IN BULK, CROP 2023

Vessel: M/T ALMA MARINE

Quantity: 6000,000 MT

B/L No. & Date: NO. 1 DD 21.09.2024 Shipper: SUNOLTA (SUISSE) SA RUE DU 23-JUIN 26,

2800 DELEMONT, SWITZERLAND

TO ORDER Consignee: Notify address: Oliva AD

> 60 Asen Yordanov Str. Lozenets district 1407 Sofia, Bulgaria, VAT: BG106013774

Port of loading: ODESA, UKRAINE Port of discharge: VARNA, BULGARIA

Vessel Tanks Nos.: 1P,2P,3P,4P,5P,1S,2S,3S,4S,5S

## RESULTS OF INSPECTION

The last three cargoes as declared by the vessel are as follows:

Ships Tanks N°	Last cargo	Second Last Cargo	Third Last Cargo
1P	GAS OIL	GAS OIL	GAS OIL
1S	GAS OIL	GAS OIL	GAS OIL
2P	GAS OIL	GAS OIL	GAS OIL
2S	GAS OIL	GAS OIL	GAS OIL
3P	GAS OIL	GAS OIL	GAS OIL
3S 08 08 078	GAS OIL	GAS OIL	GAS OIL
4P CHAR CHAR CHAR	CAS CAS CAS CAS CAS CAS OIL	GAS OIL	GAS OIL
4S	GAS OIL	GAS OIL	GAS OIL
5P 000 CRM C100 C	GAS OIL	GAS OIL	GAS OIL
5S CAR CAR CAR	GAS OIL	GAS OIL	GAS OIL

These findings are valid for the time and place of inspection only.

The certificate does not relieve the Vessel, Carrier and any other party from their contractual obligations and duties.

This certificate is electronically signed and stamped.

DATED: 21 of SEPTEMBER, 2024 For and on behalf of CISS GROUP Ukraine LLC Registered Superintendent and Surveyor Member of FOSFA







