





CISS GROUP UKRAINE LLC member of CISS GROUP Pte.Ltd. (Singapore) 5, Odessa Blv., Ovidiopol district, Lymanka village, Odessa region, 65037 inspection@ciss-group.com

CERTIFICATE No.: SGD01372

ORIGINAL

STANDARD TANK CLEANLINESS CERTIFICATE

In pursuance of an order received from our principal, requesting us to carry out inspection we hereby confirm as follows:

UKRAINIAN ORIGIN CRUDE SUNFLOWER OIL. Description of goods:

IN BULK, CROP 2023

Vessel: M/T ALMA MARINE

2300,000 MT Quantity:

B/L No. & Date: NO. 2 DD 21.09.2024 Shipper: SUNOLTA (SUISSE) SA RUE DU 23-JUIN 26,

2800 DELEMONT, SWITZERLAND

Consignee: TO ORDER Oliva AD Notify address:

60 Asen Yordanov Str.

Lozenets district 1407 Sofia, Bulgaria, VAT: BG106013774

Port of loading: ODESA, UKRAINE Port of discharge: VARNA, BULGARIA

1P,2P,3P,4P,5P,1S,2S,3S,4S,5S Vessel Tanks Nos.:

RESULTS OF INSPECTION

We hereby certify that prior to loading the ship's tanks, pumps and pipelines were visually inspected for cleanliness as far as possible and accessible: and were found empty, clean, free from harmful material and in this respect the ships tanks, pumps and pipes are suitable to receive and carry the oil. The last three cargoes as declared by the vessel are as follows:

Ships Tanks N°	Last cargo	Second Last Cargo	Third Last Cargo
1P case case case case	GAS OIL	GAS OIL	GAS OIL
18	Class class class of GAS OIL	GAS OIL	GAS OIL
2P	GAS OIL	GAS OIL	GAS OIL
2S	GAS OIL	GAS OIL	GAS OIL
3P	GAS OIL	GAS OIL	GAS OIL
3S	GAS OIL	GAS OIL	GAS OIL
4P	GAS OIL	GAS OIL	GAS OIL
4S	GAS OIL	GAS OIL	GAS OIL
5P	GAS OIL	GAS OIL	GAS OIL
5S	GAS OIL	GAS OIL	GAS OIL

These findings are valid for the time and place of inspection only.

The certificate does not relieve the Vessel, Carrier and any other party from their contractual obligations and duties.

This certificate is electronically signed and stamped.

DATED: 21 of SEPTEMBER, 2024 For and on behalf of CISS GROUP Ukraine LLC Registered Superintendent and Surveyor Member of FOSFA





