



Commodities International  
Shipping and Survey



CISS GROUP UKRAINE LLC  
member of CISS GROUP Pte.Ltd. (Singapore)  
5, Odessa Blv., Ovidiopol district,  
Lymanka village, Odessa region, 65037  
inspection@ciiss-group.com

Page 1/1

CERTIFICATE No.: SGD01376

ORIGINAL

## HOLDS CLEANLINESS INSPECTION CERTIFICATE

In pursuance of an order received from our principal, requesting us to carry out inspection we hereby confirm as follows:

Description of goods:	CRUDE SUNFLOWER OIL
Vessel:	M/T HIRA V
Quantity:	2900,000 MT
B/L No. & Date:	NO. 1 DD 05.10.2024
Shipper:	SUNOLTA (SUISSE) SA RUE DU 23-JUIN 26, 2800 DELEMONT, SWITZERLAND
Consignee:	TO ORDER
Notify address:	F.FAIGES S.L. COMMERCIO 51 43500 TORTOSA (TARRAGONE) / SPAIN
Port of loading:	ODESA, UKRAINE
Port of discharge:	SEVILLE, SPAIN
Vessel Tanks Nos.:	2P, 4P, 6P, 2S, 4S, 6S

### RESULTS OF INSPECTION

We hereby certify that prior to loading the ship's tanks, pumps and pipelines were visually inspected for cleanliness as far as possible and accessible: and were found empty, clean, free from harmful material and in this respect the ships tanks, pumps and pipes are suitable to receive and carry the oil. The last three cargoes as declared by the vessel are as follows:

SHIPS TANKS N°	LAST CARGO	SECOND LAST CARGO	THIRD LAST CARGO
2P	CSFO 94.9%	CSFO 95.9%	MTBE 96.9%
2S	CSFO 94.4%	CSFO 95.4%	MTBE 96.4%
4P	CSFO 95.7%	CSFO 89.5%	MTBE 96.8%
4S	CSFO 94.8%	CSFO 88.6%	MTBE 95.8%
6P	CSFO 94.4%	CSFO 81.4%	MTBE 96.9%
6S	CSFO 94.5%	CSFO 81.4%	MTBE 97.0%

These findings are valid for the time and place of inspection only.  
The certificate does not relieve the Vessel, Carrier and any other party from their contractual obligations and duties.

This certificate is electronically signed and stamped.

DATED: 5th of OCTOBER, 2024

For and on behalf of CISS GROUP Ukraine LLC  
Registered Superintendent and Surveyor Member of FOSFA

