

FOSFA CERTIFICATE OF COMPLIANCE, CLEANLINESS AND SUITABILITY OF SHIP'S TANK(S)

File No:	SGD01376		
Ship:	M/T HIRA V	Ships Tanks No:	2P, 4P, 6P, 2S, 4S, 6S
Owners:	HIRA SHIPPING CO LTD	Operator:	VEYSEL VARDAL GEMICILIK DENZCILIK
Inspected for cleanliness at port:	ODESA, UKRAINE	Berth:	5-6
On (Date):	02.10.2024	At (Time):	21:30

1. We have sighted a statement in the form of the FOSFA Combined Master's Certificate signed by the *Captain/First Officer or an equivalent statement signed by the *ship's Owner/authorised agent certifying that the above named ship complies with the FOSFA Qualifications and Operational Procedures for Ships Engaged in the Carriage of Oils and Fats in Bulk for Edible and Oleo-Chemical Use.
2. Prior to inspection we were informed by ship's *Captain/First Officer that the tank was
 - *a ~~stainless steel~~
 - *b mild steel coated with (description of coating) Marine line ~~new coating/recoating to be declared when appropriate/relevant~~
 - *c ~~mild steel~~

3. We received a copy of a statement signed by ship's Captain, owners or authorised agent certifying that:

- *a. ~~The immediate previous cargo in the tank was not a substance appearing on the FOSFA List of Banned Immediate Previous Cargoes in force at the date of the Bill/s of Lading and the tank complies with the Restrictions beyond the Immediate Previous Cargo as set out in the FOSFA List of Banned Immediate Previous Cargoes. The three previous cargoes carried are stated to have been:~~
- *b. The immediate previous cargo in the tank was a substance on the FOSFA List of Acceptable Previous Cargoes in force at the date of the Bill/s of Lading and the tank complies with the Restrictions beyond the Immediate Previous Cargo as set out in the FOSFA List of Acceptable Previous Cargoes. The three previous cargoes carried are stated to have been:
- *c. ~~Applicable to mild steel tanks only The three previous cargoes were oils and fats for edible and oleo chemical use and/or molasses and were stated to have been:~~
- *d. ~~Applicable to newly coated or fully recoated tanks The previous cargoes carried are stated to have been (for contamination control purposes):~~

Ships Tanks No	Last Cargo	Second Last Cargo	Third Last Cargo	Etc
2P	CSFO 94.9%	CSFO 95.9%	MTBE 96.9%	-
2S	CSFO 94.4%	CSFO 95.4%	MTBE 96.4%	-
4P	CSFO 95.7%	CSFO 89.5%	MTBE 96.8%	-
4S	CSFO 94.8%	CSFO 88.6%	MTBE 95.8%	-
6P	CSFO 94.4%	CSFO 81.4%	MTBE 96.9%	-
6S	CSFO 94.5%	CSFO 81.4%	MTBE 97.0%	-

Under the provisions of 3a. and 3b. above in the event that a cargo was less than 60% of volume of the tank, such cargo to be recorded but is not to be considered a qualifying previous cargo. Such cargo not to be a product on the FOSFA List of Banned immediate Cargoes or to be a product on the FOSFA List of Acceptable Previous Cargoes; whichever list to apply, dictated by the sales contract.

- 4 We sighted ship's log which confirmed the above information as to the previous cargoes and their respective volume in the tank.
- 5 We were informed by ship's *Captain/Chief Officer that the tank had been cleaned after the last cargo by using the following cleaning procedure:

1. BW WITH AMBIENT SW, 60 min
2. BW WITH HOT (60-70 C) SW, 90 min
3. BW WITH FW, 20 min

4. DRAINING PUMPS AND LINES, VENTILATION, MOPPING

- 6 Tank was examined internally for cleanliness and as far as could be seen was found to be clean and dry and free from harmful material and, in our opinion, in this respect based on our visual inspection and at the time of our inspection, was in a fit state to receive a cargo of CRUDE SUNFLOWER OIL in bulk.
- 7 From our inspection we found the tank construction was:

- *a ~~Stainless steel.~~
- *b Mild steel coated and as far as could be seen the coating appeared to be in sound condition with minimal mild steel exposure, without loose scale or closed blisters.
- *c ~~Mild steel and as far as could be seen appeared to be in sound condition without loose scale.~~

- 8 Ship's cargo pumps and fixed pipelines were inspected as far as possible in-situ and based on our visual inspection found to be clean and dry with no significant odour.
- 9 We were informed by the ship's C/O that the tank coils and/or heat exchangers were tested on 07.08.2024 (date) by an application of live steam/hot water to not less than 12 kPa bar for a period of 15 minutes and were found tight.
- 10 As far as could be seen from our visual inspection, the hatch covers and jointing appeared to be in sound condition, the seals and packing did not appear to contain copper or copper alloy and there was no copper or copper alloy in the pipelines, pumping system or tank internal fittings where they were in contact with cargo.

Issued by: CISS Group	(FOSFA Members Superintendent)	Captain / Chief Officer
Signed: _____	Signed: _____	

Inspection completed at 21:30 hours on 02.10.2024 (Date)

