

Commodities International Shipping and Survey







ORIGINAL

CISS GROUP UKRAINE LLC member of CISS GROUP Pte.Ltd. (Singapore)

5, Odessa Blv., Ovidiopol district, Lymanka village, Odessa region, 65037 inspection@ciss-group.com

CERTIFICATE No.: SGD01386

CERTIFICATE STATING LAST THREE CARGOES

In pursuance of an order received from our principal, requesting us to carry out inspection we

hereby confirm as follows:

CRUDE SUNFLOWERSEED OIL Description of goods:

Vessel: M/T VITIS Quantity: 5900,000 MT

B/L No. & Date: NO. 1 DD 15.10.2024 Shipper: SUNOLTA (SUISSE) SA

RUE DU 23-JUIN 26, 2800 DELEMONT

SWITZERLAND

Consignee: TO THE ORDER

Notify address: MIGASA ACEITES S.L.U. CARRETERA

MADRID - CADIZ KM 556 41703 DOS HERMANAS. SEVILLA. SPAIN

Port of loading: ODESA, UKRAINE Port of discharge: SEVILLE, SPAIN

Vessel Tanks Nos.: 1P,2P,3P,4P,5P,6P,7P,8P,9P,10P,11P

1\$,2\$,3\$,4\$,5\$,6\$,7\$,8\$,9\$,10\$,11\$.

RESULTS OF INSPECTION

The last three cargoes as declared by the vessel are as follows:

Ships Tanks N°	Last cargo	Second Last Cargo	Third Last Cargo
1P	SFSO (98%)	SFSO (98%)	SFSO (98%)
1S	SFSO (98%)	SFSO (98%)	SFSO (98%)
2P	SFSO (98%)	SFSO (98%)	SFSO (98%)
2S	SFSO (98%)	SFSO (98%)	SFSO (98%)
3P	SFSO (98%)	SFSO (98%)	SFSO (98%)
3S	SFSO (98%)	SFSO (98%)	SFSO (98%)
4P	SFSO (98%)	SFSO (98%)	SFSO (98%)
4S	SFSO (98%)	SFSO (98%)	SFSO (98%)
5P	SFSO (98%)	SFSO (98%)	SFSO (98%)
5S: 25 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	SFSO (98%)	SFSO (98%)	SFSO (98%)
On $6P^{ss}$ clear	SFSO (98%)	SFSO (98%)	SFSO (98%)
6S the cas cas cas cas cas cas	SFSO (98%)	SFSO (98%)	SFSO (98%)
TP cas cas cas cas cas cas	SFSO (98%)	SFSO (98%)	SFSO (98%)
7S crea cese crea crea crea crea crea crea	SFSO (98%)	SFSO (98%)	SFSO (98%)
8P ³⁸ Clas Clas Clas Clas Clas Clas	SFSO (96%)	SFSO (98%)	SFSO (98%)
8S TO CHEST CHEST CHEST	SFSO (96%)	SFSO (98%)	SFSO (98%)
9P	SFSO (98%)	SFSO (98%)	SFSO (98%)
9S	SFSO (98%)	SFSO (98%)	SFSO (98%)
10P	SFSO (98%)	SFSO (98%)	SFSO (98%)
10S	SFSO (98%)	SFSO (98%)	SFSO (98%)
11P	SFSO (94%)	SFSO (96%)	SFSO (94%)
115	SFSO (94%)	SFSO (95%)	SFSO (94%)

These findings are valid for the time and place of inspection only.

The certificate does not relieve the Vessel, Carrier and any other party from their contractual obligations and duties.

This certificate is electronically signed and stamped.

DATED: 15th of OCTOBER, 2024 For and on behalf of CISS GROUP Ukraine LLC Registered Superintendent and Surveyor Member of FOSFA





