





CISS GROUP UKRAINE LLC member of CISS GROUP Pte.Ltd. (Singapore) 5, Odessa Blv., Ovidiopol district, Lymanka village, Odessa region, 65037 inspection@ciss-group.com

**CERTIFICATE No.: SGD01402** 

**ORIGINAL** 

## **VESSEL'S DRY AND CLEAN TANKS CERTIFICATE**

In pursuance of an order received from our principal, requesting us to carry out inspection we hereby confirm as follows:

Description of goods: CRUDE SUNFLOWERSEED OIL

Vessel: M/T BARBAROS HAYRETTIN VARDAL

Quantity: 5400,000MT

B/L No. & Date: NO. 1 DD 11.11.2024 Shipper: SUNOLTA (SUISSE) SA

RUE DU 23-JUIN 26, 2800 DELEMONT,

SWITZERLAND

Consignee: TO THE ORDER

Notify address: MIGASA ACEITES S.L.U.

CARRETERA MADRID - CADIZ KM 556 41703 DOS HERMANAS. SEILLA. SPAIN

Port of loading: ODESA, UKRAINE

Port of discharge: SEVILLE, SPAIN
Vessel Tanks Nos.: 1P,2P,3P,4P,5P,1S,2S,3S,4S,5S

## **RESULTS OF INSPECTION**

The last three cargoes as declared by the vessel are as follows:

SHIPS TANKS N°	LAST CARGO	SECOND LAST CARGO	THIRD LAST CARGO
1P	CSFSO %91.9	CSFSO %96	CSS %60.0
1S	CSFSO %91.9	CSFSO %96.4	CSS %60.0
2P 4	CSFSO %93.0	CSFSO %96.1	CSS %74.9
2S	CSFSO %93.9	CSFSO %96.1	CSS %75.1
3P	CSFSO %93.0	CSFSO %95.1	FAME%87.9
38	CSFSO %92.7	CSFSO %94.9	FAME%87.9
4P CAS	CSFSO %87.9	CSFSO %87.1	CSS %60.4
4S	CSFSO %90.5	CSFSO %87.8	CSS %60.4
5P Class Cla	CSFSO %89.3	CSFSO %86.7	CSS %66.2
5S CASE CASE CASE CASE CASE CASE CASE CAS	CSFSO %90.9	CSFSO %87.8	CSS %71.2

These findings are valid for the time and place of inspection only.

The certificate does not relieve the Vessel, Carrier and any other party from their contractual obligations and duties.

This certificate is electronically signed and stamped.



DATED: 11th of NOVEMBER, 2024
For and on behalf of CISS GROUP Ukraine LLC
Registered Superintendent and Surveyor Member of FOSFA



