



Commodities International  
Shipping and Survey



FOSFA  
INTERNATIONAL

Page

1/1

CISS GROUP UKRAINE LLC  
member of CISS GROUP Pte.Ltd. (Singapore)  
5, Odessa Blv., Ovidiopol district,  
Lymanka village, Odessa region, 65037  
inspection@ciiss-group.com

CERTIFICATE No.: SGD01417

ORIGINAL

## ORIGINAL TANK INSPECTION CERTIFICATE

In pursuance of an order received from our principal, requesting us to carry out inspection we hereby confirm as follows:

Description of goods:	UKRAINIAN ORIGIN OF CRUDE SUNFLOWER SEED OIL, IN BULK
Vessel:	M/T SEAVEN VOYAGER
Quantity:	6100,000 MT
B/L No. & Date:	NO. 1 AND 2 DD 06.12.2024
Shipper:	SUNOLTA (SUISSE) SA RUE DU 23-JUIN 26, 2800 DELEMONT, SWITZERLAND REG.NO. CHE-345.676.000
Consignee:	TO ORDER
Notify address:	1 - VSS GENERAL TRADING FZCO DSO - IFZA, TECHNO HUB-1 BA04 DSO, DUBAI / UNITED ARAB EMIRATES PO BOX: 416119 2 - PIER AGRO GIDA SAN. VE TIC. A.S. ADANA YUMURTALIK SERBEST BOLGE SUBESI SARIMAZI SERBEST BOLGE MAH. ADANA YUMURTALIK SERBEST BOLGESI YUMURTALIK / ADANA / TURKIYE
Port of loading:	ODESA, UKRAINE
Port of discharge:	CEYHAN / TOROS PORT, TURKEY
Vessel Tanks Nos.:	1P, 2P, 3P, 4P, 5P, 6P, 1S, 2S, 3S, 4S, 5S, 6S, SS

### RESULTS OF INSPECTION

We hereby certify that prior to loading the ship's tanks, pumps and pipelines were visually inspected for cleanliness as far as possible and accessible: and were found empty, clean, free from harmful material and in this respect the ships tanks, pumps and pipes are suitable to receive and carry the oil. The last three cargoes as declared by the vessel are as follows:

Ships Tanks N°	Last cargo	Second Last Cargo	Third Last Cargo
1P	ULSD (95%)	ULSD (95%)	ULSD (98%)
1S	ULSD (95%)	ULSD (95%)	ULSD (98%)
2P	ULSD (95%)	ULSD (95%)	ULSD (98%)
2S	ULSD (95%)	ULSD (95%)	ULSD (98%)
3P	ULSD (95%)	ULSD (95%)	ULSD (98%)
3S	ULSD (95%)	ULSD (95%)	ULSD (98%)
4P	ULSD (95%)	ULSD (95%)	ULSD (98%)
4S	ULSD (95%)	ULSD (95%)	ULSD (98%)
5P	ULSD (95%)	ULSD (95%)	ULSD (98%)
5S	ULSD (95%)	ULSD (95%)	ULSD (98%)
6P	ULSD (95%)	ULSD (95%)	ULSD (98%)
6S	ULSD (95%)	ULSD (95%)	ULSD (98%)
Slop S	ULSD (90%)	ULSD (85%)	ULSD (70%)

These findings are valid for the time and place of inspection only.

The certificate does not relieve the Vessel, Carrier and any other party from their contractual obligations and duties.

This certificate is electronically signed and stamped.

DATED: 6th of DECEMBER, 2024

For and on behalf of CISS GROUP Ukraine LLC  
Registered Superintendent and Surveyor Member of FOSFA

