





CISS GROUP UKRAINE LLC member of CISS GROUP Pte.Ltd. (Singapore) 5, Odessa Blv., Ovidiopol district, Lymanka village, Odessa region, 65037 inspection@ciss-group.com

CERTIFICATE No.: SGD01450

ORIGINAL

HOLDS CLEANLINESS INSPECTION CERTIFICATE

In pursuance of an order received from our principal, requesting us to carry out inspection we hereby confirm as follows:

Description of goods: CRUDE SUNFLOWERSEED OIL, IN BULK OF EDIBLE GRADE

(FIT FOR HUMAN CONSUMPTION AFTER APPROPRIATE REFINING)

Vessel: M/T VITIS
Quantity: 5900,000 MT

B/L No. & Date: NO. 1 DD 11.03.2025 Shipper: SUNOLTA (SUISSE) SA

RUE DU 23-JUIN 26, 2800 DELEMONT, SWITZERLAND

REG.NO. CHE-345.676.000

ON BEHALF OF TOI COMMODITIES SA, CHEMIN DU POMMIER 42, KYOTO,

1218 LE GRAND-SACONNEX, SWITZERLAND

Consignee: TO ORDER

Notify address: TOI COMMODITIES SA

CHEMIN DU POMMIER 42, KYOTO,

1218 LE GRAND-SACONNEX, SWITZERLAND

Port of loading: ODESA, UKRAINE

Port of discharge: CONSTANTA, ROMANIA

Vessel Tanks Nos.: 1P, 2P, 3P, 4P, 5P, 6P, 7P,8P, 9P, 10P, 11P,1S, 2S, 3S, 4S, 5S, 6S,

7S, 8S, 9S, 10S, 11S

RESULTS OF INSPECTION

We hereby certify that prior to loading the ship's tanks, pumps and pipelines were visually inspected for cleanliness as far as possible and accessible: and were found empty, clean, free from harmful material and in this respect the ships tanks, pumps and pipes are suitable to receive and carry the oil. The last three cargoes as declared by the vessel are as follows:

Ships Tanks N°	Last cargo	Second Last Cargo	Third Last Cargo
1P	SFSO (98%)	SFSO (98%)	SFSO (98%)
1S	SFSO (98%)	SFSO (98%)	SFSO (98%)
2P	SFSO (98%)	SFSO (98%)	SFSO (98%)
2S	SFSO (98%)	SFSO (98%)	SFSO (98%)
3P	SFSO (98%)	SFSO (98%)	SFSO (98%)
3S	SFSO (98%)	SFSO (98%)	SFSO (98%)
4P	SFSO (98%)	SFSO (98%)	SFSO (98%)
4S	SFSO (98%)	SFSO (98%)	SFSO (98%)
5P	SFSO (98%)	SFSO (98%)	SFSO (98%)







Commodities International Shipping and Survey





CERTIFICATE No.: SGD01450

ORIGINAL

CISS GROUP UKRAINE LLC member of CISS GROUP Pte.Ltd. (Singapore) 5, Odessa Blv., Ovidiopol district, Lymanka village, Odessa region, 65037 inspection@ciss-group.com

5S	SFSO (98%)	SFSO (98%)	SFSO (98%)
6P	SFSO (98%)	SFSO (98%)	SFSO (98%)
6S	SFSO (98%)	SFSO (98%)	SFSO (98%)
7P	SFSO (98%)	SFSO (98%)	SFSO (98%)
7S	SFSO (98%)	SFSO (98%)	SFSO (98%)
8P	SFSO (96%)	SFSO (98%)	SFSO (98%)
8S	SFSO (96%)	SFSO (98%)	SFSO (98%)
9P	SFSO (98%)	SFSO (98%)	SFSO (98%)
9S	SFSO (98%)	SFSO (98%)	SFSO (98%)
10P	SFSO (98%)	SFSO (98%)	SFSO (98%)
10S	SFSO (98%)	SFSO (98%)	SFSO (98%)
11P	SFSO (94%)	SFSO (96%)	SFSO (94%)
11S	SFSO (94%)	SFSO (95%)	SFSO (94%)

These findings are valid for the time and place of inspection only.

The certificate does not relieve the Vessel, Carrier and any other party from their contractual obligations and duties.

This certificate is electronically signed and stamped.

DATED: 11th of MARCH, 2025 For and on behalf of CISS GROUP Ukraine LLC Registered Superintendent and Surveyor Member of FOSFA





