

Commodities International Shipping and Survey







ORIGINAL

CISS GROUP UKRAINE LLC member of CISS GROUP Pte.Ltd. (Singapore)

5, Odessa Blv., Ovidiopol district, Lymanka village, Odessa region, 65037 inspection@ciss-group.com

CERTIFICATE No.: SGD01468

LAST THREE CARGOES CERTIFICATE

In pursuance of an order received from our principal, requesting us to carry out inspection we

hereby confirm as follows:

CRUDE SUNFLOWERSEED OIL Description of goods:

Vessel: M/T VITIS Quantity: 5900,000 MT

B/L No. & Date: NO. 1 DD 14.04.2025 Shipper: SUNOLTA (SUISSE) SA

RUE DU 23-JUIN 26, 2800 DELEMONT

SWITZERLAND

Consignee: TO THE ORDER

Notify address: MIGASA ACEITES S.L.U. CARRETERA

> MADRID - CADIZ KM 556 41703 DOS HERMANAS. SEVILLA. SPAIN.

Port of loading: ODESA, UKRAINE

Port of discharge: SEVILLE, SPAIN

Vessel Tanks Nos.: 1P, 2P, 3P, 4P, 5P, 6P, 7P,8P, 9P, 10P, 11P,1S, 2S, 3S, 4S, 5S, 6S, 7S,

8S, 9S, 10S, 11S

RESULTS OF INSPECTION

The last three cargoes as declared by the vessel are as follows:

| SHIPS TANKS N° | LAST CARGO | SECOND LAST CARGO | THIRD LAST CARGO |
|----------------|------------|-------------------|------------------|
| 1P | SFSO (98%) | SFSO (98%) | SFSO (98%) |
| 1S | SFSO (98%) | SFSO (98%) | SFSO (98%) |
| 2P | SFSO (98%) | SFSO (98%) | SFSO (98%) |
| 2S | SFSO (98%) | SFSO (98%) | SFSO (98%) |
| 3P | SFSO (98%) | SFSO (98%) | SFSO (98%) |
| 3S | SFSO (98%) | SFSO (98%) | SFSO (98%) |
| 4P | SFSO (98%) | SFSO (98%) | SFSO (98%) |
| 48 | SFSO (98%) | SFSO (98%) | SFSO (98%) |
| 5P | SFSO (98%) | SFSO (98%) | SFSO (98%) |
| 5S | SFSO (98%) | SFSO (98%) | SFSO (98%) |
| 6P | SFSO (98%) | SFSO (98%) | SFSO (98%) |
| 6S | SFSO (98%) | SFSO (98%) | SFSO (98%) |
| 7P 7P | SFSO (98%) | SFSO (98%) | SFSO (98%) |
| 7S 25 25 25 | SFSO (98%) | SFSO (98%) | SFSO (98%) |
| 8P | SFSO (96%) | SFSO (98%) | SFSO (98%) |
| 8S | SFSO (96%) | SFSO (98%) | SFSO (98%) |
| 9P | SFSO (98%) | SFSO (98%) | SFSO (98%) |
| 98 | SFSO (98%) | SFSO (98%) | SFSO (98%) |
| 10P | SFSO (98%) | SFSO (98%) | SFSO (98%) |
| 10S | SFSO (98%) | SFSO (98%) | SFSO (98%) |
| 11P | SFSO (94%) | SFSO (96%) | SFSO (94%) |
| 11S | SFSO (94%) | SFSO (95%) | SFSO (94%) |

These findings are valid for the time and place of inspection only.

The certificate does not relieve the Vessel, Carrier and any other party from their contractual obligations and duties.



This certificate is electronically signed and stamped.

DATED: 14th of APRIL, 2025 For and on behalf of CISS GROUP Ukraine LLC Registered Superintendent and Surveyor Member of FOSFA



