

CISS GROUP UKRAINE LLC

inspection@ciss-group.com

Commodities International Shipping and Survey







Page

1/1

member of CISS GROUP Pte.Ltd. (Singapore)

5, Odessa Blv., Ovidiopol district,
Lymanka village, Odessa region, 65037

CERTIFICATE No.: SGD01468

ORIGINAL

VESSEL'S DRY AND CLEAN TANKS CERTIFICATE

In pursuance of an order received from our principal, requesting us to carry out inspection we hereby confirm as follows:

Description of goods: CRUDE SUNFLOWERSEED OIL

Vessel: M/T VITIS
Quantity: 5900,000 MT

B/L No. & Date: NO. 1 DD 14.04.2025 Shipper: SUNOLTA (SUISSE) SA

RUE DU 23-JUIN 26, 2800 DELEMONT.

SWITZERLAND

Consignee: TO THE ORDER

Notify address: MIGASA ACEITES S.L.U. CARRETERA

MADRID - CADIZ KM 556 41703 DOS HERMANAS. SEVILLA. SPAIN.

Port of loading: ODESA, UKRAINE Port of discharge: SEVILLE, SPAIN

Vessel Tanks Nos.: 1P, 2P, 3P, 4P, 5P, 6P, 7P,8P, 9P, 10P, 11P,1S, 2S, 3S, 4S, 5S, 6S, 7S,

8S, 9S, 10S, 11S

RESULTS OF INSPECTION

The last three cargoes as declared by the vessel are as follows:

| SHIPS TANKS N° | LAST CARGO | SECOND LAST CARGO | THIRD LAST CARGO |
|------------------------|------------|-------------------|------------------|
| 1P | SFSO (98%) | SFSO (98%) | SFSO (98%) |
| 18 | SFSO (98%) | SFSO (98%) | SFSO (98%) |
| 2P | SFSO (98%) | SFSO (98%) | SFSO (98%) |
| 2S | SFSO (98%) | SFSO (98%) | SFSO (98%) |
| 3P | SFSO (98%) | SFSO (98%) | SFSO (98%) |
| 38 | SFSO (98%) | SFSO (98%) | SFSO (98%) |
| 4P- | SFSO (98%) | SFSO (98%) | SFSO (98%) |
| 48 | SFSO (98%) | SFSO (98%) | SFSO (98%) |
| 5P | SFSO (98%) | SFSO (98%) | SFSO (98%) |
| 5S | SFSO (98%) | SFSO (98%) | SFSO (98%) |
| 6P | SFSO (98%) | SFSO (98%) | SFSO (98%) |
| 6S | SFSO (98%) | SFSO (98%) | SFSO (98%) |
| 7P Cres Cres Cres Cres | SFSO (98%) | SFSO (98%) | SFSO (98%) |
| 7S | SFSO (98%) | SFSO (98%) | SFSO (98%) |
| 8P | SFSO (96%) | SFSO (98%) | SFSO (98%) |
| 8S | SFSO (96%) | SFSO (98%) | SFSO (98%) |
| 9P | SFSO (98%) | SFSO (98%) | SFSO (98%) |
| 98 | SFSO (98%) | SFSO (98%) | SFSO (98%) |
| 10P | SFSO (98%) | SFSO (98%) | SFSO (98%) |
| 10S | SFSO (98%) | SFSO (98%) | SFSO (98%) |
| 11P | SFSO (94%) | SFSO (96%) | SFSO (94%) |
| 118 | SFSO (94%) | SFSO (95%) | SFSO (94%) |

These findings are valid for the time and place of inspection only.

The certificate does not relieve the Vessel, Carrier and any other party from their contractual obligations and duties.

This certificate is electronically signed and stamped.

DATED: 14th of APRIL, 2025
For and on behalf of CISS GROUP Ukraine LLC
Registered Superintendent and Surveyor Member of FOSFA





