



Commodities International
Shipping and Survey



Page 1/2

CISS GROUP UKRAINE LLC
member of CISS GROUP Pte.Ltd. (Singapore)
5, Odessa Blv., Ovidiopol district,
Lymanka village, Odessa region, 65037
inspection@ciiss-group.com

CERTIFICATE No.: SGD01484

ORIGINAL

ORIGINAL TANK INSPECTION CERTIFICATE

In pursuance of an order received from our principal, requesting us to carry out inspection we hereby confirm as follows:

Description of goods:	CRUDE SUNFLOWER SEED OIL, IN BULK
Vessel:	M/T VITIS
Quantity:	5900,000 MT
B/L No. & Date:	NO. 1 AND 2 DD 08.05.2025
Shipper:	SUNOLTA OU KESKLINNA LINNAOSA, JOE TN 4C 10151, HARJU MAAKOND TALLINN, ESTONIA
Consignee:	TO ORDER
Notify address:	PIER AGRO GIDA SAN. VE TIC.A.S. ADANA YUMURTALIK SERBEST BOLGE SB. ADRESS: SARIMAZI SERBEST BOLGE MAH. ADANA YUMURTALIK SERBEST BOLGESI CEYHAN – ADANA
Port of loading:	ODESA, UKRAINE
Port of discharge:	ISKENDERUN TURKIYE TOROS PORT (PIER AGRO TERMINAL)
Vessel Tanks Nos.:	1P, 2P, 3P, 4P, 5P, 6P, 7P, 8P, 9P, 10P, 11P, 1S, 2S, 3S, 4S, 5S, 6S, 7S, 8S, 9S, 10S, 11S

RESULTS OF INSPECTION

We hereby certify that prior to loading the ship's tanks, pumps and pipelines were visually inspected for cleanliness as far as possible and accessible: and were found empty, clean, free from harmful material and in this respect the ships tanks, pumps and pipes are suitable to receive and carry the oil. The last three cargoes as declared by the vessel are as follows:

Ships Tanks N°	Last cargo	Second Last Cargo	Third Last Cargo
1P	SFSO (98%)	SFSO (98%)	SFSO (98%)
1S	SFSO (98%)	SFSO (98%)	SFSO (98%)
2P	SFSO (98%)	SFSO (98%)	SFSO (98%)
2S	SFSO (98%)	SFSO (98%)	SFSO (98%)
3P	SFSO (98%)	SFSO (98%)	SFSO (98%)
3S	SFSO (98%)	SFSO (98%)	SFSO (98%)
4P	SFSO (98%)	SFSO (98%)	SFSO (98%)
4S	SFSO (98%)	SFSO (98%)	SFSO (98%)
5P	SFSO (98%)	SFSO (98%)	SFSO (98%)
5S	SFSO (98%)	SFSO (98%)	SFSO (98%)
6P	SFSO (98%)	SFSO (98%)	SFSO (98%)
6S	SFSO (98%)	SFSO (98%)	SFSO (98%)





**Commodities International
Shipping and Survey**



Page 2/2

CISS GROUP UKRAINE LLC
member of CISS GROUP Pte.Ltd. (Singapore)
5, Odessa Blv., Ovidiopol district,
Lymanka village, Odessa region, 65037
inspection@ciiss-group.com

CERTIFICATE No.: SGD01484

ORIGINAL

7P	SFSO (98%)	SFSO (98%)	SFSO (98%)
7S	SFSO (98%)	SFSO (98%)	SFSO (98%)
8P	SFSO (96%)	SFSO (98%)	SFSO (98%)
8S	SFSO (96%)	SFSO (98%)	SFSO (98%)
9P	SFSO (98%)	SFSO (98%)	SFSO (98%)
9S	SFSO (98%)	SFSO (98%)	SFSO (98%)
10P	SFSO (98%)	SFSO (98%)	SFSO (98%)
10S	SFSO (98%)	SFSO (98%)	SFSO (98%)
11P	SFSO (94%)	SFSO (96%)	SFSO (94%)
11S	SFSO (94%)	SFSO (95%)	SFSO (94%)

These findings are valid for the time and place of inspection only.

The certificate does not relieve the Vessel, Carrier and any other party from their contractual obligations and duties.

This certificate is electronically signed and stamped.

DATED: 8th of MAY, 2025

For and on behalf of CISS GROUP Ukraine LLC
Registered Superintendent and Surveyor Member of FOSFA

