



**Commodities International  
Shipping and Survey**



**FOSFA  
INTERNATIONAL**

Page

1/1

**CISS GROUP UKRAINE LLC**  
member of **CISS GROUP Pte.Ltd. (Singapore)**  
5, Odessa Blv., Ovidiopol district,  
Lymanka village, Odessa region, 65037  
inspection@ciiss-group.com

**CERTIFICATE No.: SGD01494**

**ORIGINAL**

## **TANKS CLEANLINESS INSPECTION CERTIFICATE**

In pursuance of an order received from our principal, requesting us to carry out inspection we hereby confirm as follows:

Description of goods:

CRUDE SUNFLOWERSEEDOIL IN BULK

Vessel:

M/T VITIS

Quantity:

5900,000 MT

B/L No. & Date:

NO. 1 DD 29.05.2025

Shipper:

SUNOLTA OU

KESKLINNA LINNAOSA, JOE TN 4C

10151, HARJU MAAKOND

TALLINN, ESTONIA

Consignee:

TO ORDER

Notify address:

SOVENA OILSEEDS PORTUGAL SA

RUA DR. ANTONIO LOUREIRO BORGES, N°2

EDIFICIO ARQUIPARQUE, N°2-3°

MIRAFLORES 1495-131 ALGES - PORTUGAL

Port of loading:

ODESA, UKRAINE

Port of discharge:

LISBON - PORTUGAL

Vessel Tanks Nos.:

1P,2P,3P,4P,5P,6P,7P,8P,9P,10P,11P,

1S,2S,3S,4S,5S,6S,7S,8S,9S,10S,11S.

### **RESULTS OF INSPECTION**

We hereby certify that prior to loading the ship's tanks, pumps and pipelines were visually inspected for cleanliness as far as possible and accessible: and were found empty, clean, free from harmful material and in this respect the ships tanks, pumps and pipes are suitable to receive and carry the oil. The last three cargoes as declared by the vessel are as follows:

SHIPS TANKS N°	LAST CARGO	SECOND LAST CARGO	THIRD LAST CARGO
1P	SFSO (98%)	SFSO (98%)	SFSO (98%)
1S	SFSO (98%)	SFSO (98%)	SFSO (98%)
2P	SFSO (98%)	SFSO (98%)	SFSO (98%)
2S	SFSO (98%)	SFSO (98%)	SFSO (98%)
3P	SFSO (98%)	SFSO (98%)	SFSO (98%)
3S	SFSO (98%)	SFSO (98%)	SFSO (98%)
4P	SFSO (98%)	SFSO (98%)	SFSO (98%)
4S	SFSO (98%)	SFSO (98%)	SFSO (98%)
5P	SFSO (98%)	SFSO (98%)	SFSO (98%)
5S	SFSO (98%)	SFSO (98%)	SFSO (98%)
6P	SFSO (98%)	SFSO (98%)	SFSO (98%)
6S	SFSO (98%)	SFSO (98%)	SFSO (98%)
7P	SFSO (98%)	SFSO (98%)	SFSO (98%)
7S	SFSO (98%)	SFSO (98%)	SFSO (98%)
8P	SFSO (96%)	SFSO (98%)	SFSO (98%)
8S	SFSO (96%)	SFSO (98%)	SFSO (98%)
9P	SFSO (98%)	SFSO (98%)	SFSO (98%)
9S	SFSO (98%)	SFSO (98%)	SFSO (98%)
10P	SFSO (98%)	SFSO (98%)	SFSO (98%)
10S	SFSO (98%)	SFSO (98%)	SFSO (98%)
11P	SFSO (94%)	SFSO (96%)	SFSO (94%)
11S	SFSO (94%)	SFSO (95%)	SFSO (94%)

These findings are valid for the time and place of inspection only.

The certificate does not relieve the Vessel, Carrier and any other party from their contractual obligations and duties.

**This certificate is electronically signed and stamped.**

**DATED: 29th of MAY, 2025**

**For and on behalf of CISS GROUP Ukraine LLC**

**Registered Superintendent and Surveyor Member of FOSFA**

