

INSPECTION REPORT

Client : XXXXXX
Description of goods : EQUIPMENT, TRANSFORMER OIL PURIFICATION PLANT
Place of inspection : SOVMORTRANS terminal, ODESSA
Date of inspection : 02/03/2012

In accordance with instructions received from Messrs. XXXXXXXXXXXX, we have attended inspection at loading of containers with equipments (**TRANSFORMER OIL PURIFICATION PLANT**) for the purpose of performing inspection of above mentioned cargo as per scope of inspection received.

Inspection was performed in presence of Messrs. XXXXXXXXXXXX. representatives.

1. TIME SHEET OF INSPECTION:

Inspection commenced	02/03/2012 at 09:30 HRS LT
Inspection completed	02/03/2012 at 11:10 HRS LT

This is to report that we have attended the above mentioned inspection and attest the following:

2. VISUAL CONDITION OF CONTAINERS and EQUIPMENT:

The inspected 1x 20 Ft containers were visually checked on visually accessible parts for technical condition prior to and upon completion of load and found to be in order. The inspected equipment visually corresponds to the information stated in the supplied documents.

PACKING:

Equipment (transformer oil purification plant) was packed into 1x 20 Ft containers, fixed by two polipropilen ropes and wood blocks on the floor. All fixing details were found to be intact and in order. Shifting of the cargo was not noted.

3. LOADING OPERATIONS:

During loading operations equipment (transformer oil purification plant) was loaded with our constant supervision using forklift loader.

4. CONDITION OF CARGO AFTER DISCHARGE:

During the discharge from car and loading to the container equipment has not damaged (see photos attached).



View of equipment



View of equipment

5. PHOTO REPORT:

The following photos were taken during the inspection:



Container No. CRXU 106466-7



Container No. CRXU 106466-7



Cargo fixing in container



Cargo fixing in container



Packing



Packing



Sealed container with cargo



CISS Seal



Machine detail



Machine detail

Discharge operations



Machine detail



Machine detail

The above given descriptions and data are valid for the time and place of Inspection only.

This inspection has been performed on the goods for which it was requested according to our professional standards and to the best of our knowledge on the date and at the place it was performed, within the scope of instructions received. This inspection does not release seller(s) and/or supplier(s) and/or shipper(s) and/or other parties involved from their respective contractual obligations and does not prejudice the buyer(s)/receiver(s)' right to claim, under applicable law and contract, compensation from seller(s)/supplier(s)/shipper(s) regarding any defects not detected during our inspection or occurring thereafter.

This inspection is also subject to CISS Terms and Conditions of Business (<http://www.ciiss-group.com>). Headings and titles in this certificate/report are for reference only and the findings contained herein prevail as stated.

Signed and dated in
Odessa
02.03.2012



FOR AND ON BEHALF OF
CISS (Ukraine)

It's shipping & survey